



BMW X3 (KLL): 1YGT847

Vinnumber:	WBAUZ35000NE43592	Versionname:	X3 (G01) 2.0d xDrive 20d 190pk/cv 5p Aut.
First Registrationdate:	8/10/2019	Fiscalpower:	
Expertise Mileage:	140871	Power Kw:	140
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	in 16000 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

245/50/19/105 V			
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R. Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R. Continental: 5 mm
Tyre profile depth FL			6.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			245/50 R 19 105 V
Tyre size FR			245/50 R 19 105 V
Tyre size RL			245/50 R 19 105 V
Tyre size RR			245/50 R 19 105 V
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Seat cover RR, Incomplete, Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)



Shutter / cover F, Missing, Replace



Wing RL, Dent(s), Acceptable



Door RL, Scratch(es), Acceptable



Wing trim RL, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Internal boot lining L, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Spot repair



Alloy rim RR, Scratch(es), Acceptable



Wing RR, Dent(s) and scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Acceptable

