



BMW Serie 3 Berlina E90 Diesel

320d Eletta 177cv

VIN NO WBAVG91060VG56114

Registration Number DY803NS



MOT Date

2023-09-14

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2009-09-11

Odometer Reading

243137 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250910142925
Inspection Date / Place	2025-09-10 / BCA Lodi	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	4
Body Type	Sedan	Drive Train	Rear
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	131

Prices

Reserve Price	4,200	Green	3,500
---------------	-------	-------	-------

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Volante multifuncion	Remote central locking
Stability control	Power assisted steering	Digital Radio	Remote adjusting wing mirrors
Trip Computer			


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	BRIDGESTONE BRIDGESTONE-TURANZA ER300A	225/45//R17 - 94Y / 2 mm
	BRIDGESTONE BRIDGESTONE-TURANZA ER300A	225/45//R17 - 94Y / 2 mm
	BRIDGESTONE BRIDGESTONE-TURANZA ER300A	225/45//R17 - 94Y / 2 mm
	BRIDGESTONE BRIDGESTONE-TURANZA ER300A	225/45//R17 - 94Y / 2 mm

Cosmetic Damage

18 Danni



0 Danni



Component	Damage	Comments	Repair Type	Repair Costs
1 Hood	Bodywork / Dent			0.00
2 Bumper / Front	Paint / Chipping			0.00
3 Rim / Front Right	Out of Bodywork / Scratch			0.00
4 Fender / Front Right	Bodywork / Dent			0.00
5 Rim / Front Left	Out of Bodywork / Scratch			0.00
6 Fender / Back Left	Bodywork / Dent / Dent			0.00
7 Rim / Back Left	Out of Bodywork / Scratch			0.00
8 Fender / Back Right	Bodywork / Dent			0.00
9 Rim / Back Right	Out of Bodywork / Scratch			0.00
10 Door / Back Right	Bodywork / Dent			0.00
11 Door / Back Right	Paint / Scratch / Line			0.00
12 Door / Front Right	Bodywork / Dent			0.00

13	Hood	Paint / Chipping	0.00
14	Door / Front Left	Paint / Chipping	0.00
15	Door / Back Left	Paint / Chipping	0.00
16	Hood	Bodywork / Dent / Hail Area	0.00
17	Windshield / Front	Glass Break	0.00
18	Pillar / Front Right	Bodywork / Poor Previous Repair	0.00
Net Total			0.00 €



1. Hood
Bodywork / Dent -
0.00



2. Bumper / Front
Paint / Chipping -
0.00



3. Rim / Front Right
Out of Bodywork / Scratch -
0.00




4. Fender / Front Right
Bodywork / Dent -
0.00



5. Rim / Front Left
Out of Bodywork / Scratch -
0.00




6. Fender / Back Left
Bodywork / Dent / Dent -
0.00




7. Rim / Back Left
Out of Bodywork / Scratch -
0.00




8. Fender / Back Right
Bodywork / Dent -
0.00




9. Rim / Back Right
Out of Bodywork / Scratch -
0.00



10. Door / Back Right
Bodywork / Dent -
0.00



11. Door / Back Right
Paint / Scratch / Line -
0.00



12. Door / Front Right
Bodywork / Dent -
0.00



13. Hood
Paint / Chipping -
0.00



14. Door / Front Left
Paint / Chipping -
0.00



15. Door / Back Left
Paint / Chipping -
0.00



16. Hood
Bodywork / Dent / Hail Area -
0.00



17. Windshield / Front
Glass Break -
0.00



18. Pillar / Front Right
Bodywork / Poor Previous Repair -
0.00

Mechanical Condition

Engine			
Engine Starts	✓	Vehicle Start - up	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
AC / Heating System	✓	Other Equipments	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested