



BMW X3 X3 xDrive20d Aut.

VIN NO WBAWY310200A76421
Registration Number 0200A76421



MOT Date

2025-11-01

Last Service

2021-11-15

Number of Owners

2

Last Service Mileage

127679

Number of Keys

2

First Registration Date

2012-12-17

Odometer Reading

149338 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250829134408
Inspection Date / Place	2025-08-29 / ARS Altmann AG Riedstadt	Cosmetic Grade	5

Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	147
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			







Equipment

Trip Computer	Alloys wheels	Bluetooth telephone interface	Diesel particulate filter
Headlamp wash/wipe	Remote central locking	Satellite navigation	Xenon headlamps
Radio	Airbag Status	Anti-lock braking	Cruise control
Front parking sensors	Remote adjusting wing mirrors	Roof rails	Stability control
Leather steering wheel	Rear parking sensors		

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

22 Schäden




2 Schäden



Component		Damage	Comments
1	Hood	Paint / Stone Chip	
2	Fog Light / Front Right	Bodywork / Breakage / Hole	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Rim / Front Left	Out of Bodywork / Scratch	
6	Door / Front Left	Bodywork / Dent / Dent	
7	Door / Front Left	Paint / Scratch / Scuff	
8	Door / Back Left	Bodywork / Dent / Dent	
9	Panel Filling / Front Left	Interior / Scratched	
10	Roof	Paint / Scratch / Scuff	
11	Rim / Back Left	Out of Bodywork / Scratch	
12	Door / Back Left	Bodywork / Dent / Dent	
13	Bumper / Back	Paint / Scratch / Scuff	


14	Bumper / Back	Paint / Scratch / Scuff
15	Rear Window / Back	Glass Break / Scratch / Scratch
16	Bumper / Back	Paint / Scratch / Scuff
17	Wing Expander / Back Right	Paint / Scratch / Scuff
18	Door / Back Right	Bodywork / Dent / Dent
19	Seat / Back Right	Interior / Scraped
20	Pillar / Front Right	Paint / Scratch / Scuff
21	Door / Front Right	Paint / Scratch / Scuff
22	Mirror / Front Right	Paint / Scratch / Scuff
23	Rim / Front Right	Out of Bodywork / Scratch
24	Fender / Front Right	Paint / Scratch / Scuff



1. Hood
Paint / Stone Chip -



2. Fog Light / Front Right
Bodywork / Breakage / Hole -



3. Bumper / Front
Paint / Scratch / Scuff -



4. Bumper / Front
Paint / Scratch / Scuff -



5. Rim / Front Left
Out of Bodywork / Scratch -




6. Door / Front Left
Bodywork / Dent / Dent -



7. Door / Front Left
Paint / Scratch / Scuff -




8. Door / Back Left
Bodywork / Dent / Dent -



9. Panel Filling / Front Left
Interior / Scratched -




10. Roof
Paint / Scratch / Scuff -



11. Rim / Back Left
Out of Bodywork / Scratch -



12. Door / Back Left
Bodywork / Dent / Dent -



13. Bumper / Back
Paint / Scratch / Scuff -



14. Bumper / Back
Paint / Scratch / Scuff -




15. Rear Window / Back
Glass Break / Scratch / Scratch -



16. Bumper / Back
Paint / Scratch / Scuff -



17. Wing Expander / Back Right
Paint / Scratch / Scuff -



18. Door / Back Right
Bodywork / Dent / Dent -




19. Seat / Back Right
Interior / Scraped -



20. Pillar / Front Right
Paint / Scratch / Scuff -




21. Door / Front Right
Paint / Scratch / Scuff -



22. Mirror / Front Right
Paint / Scratch / Scuff -



23. Rim / Front Right
Out of Bodywork / Scratch -



24. Fender / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Other Equipments	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)