



BMW X2: 2AAT185

Vinnnumber:	WBAYK510905T04520	Versionname:	sDrive18d 100kW
First Registrationdate:	2/02/2021	Fiscalpower:	
Expertise Mileage:	79396	Power Kw:	100
Bodytype:		Body colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3829
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

225/55/17/97 H				
Winter tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 17 97 H
Tyre size FR				225/55 R 17 97 H
Tyre size RL				225/55 R 17 97 H
Tyre size RR				225/55 R 17 97 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit:	No	Compressor:	No
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	202,58
Interior, Worn, Acceptable	0,00



Bonnet, Chemical polution, Acceptable 0,00



Windscreen, Repaired, Acceptable 0,00



Step L, Scratch(es), Acceptable 0,00



Tyre repair kit, Missing, Replace 0,00



Bumper R, Scratch(es), Acceptable 0,00



Step R, Scratch(es), Acceptable 0,00



Door RR, Dent(s) and scratch(es), Spot repair 202,58

