

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	304821
License plate	2CSL161
Vehicle identification number	WBAYN910405V30396
Dossier	2022 297 089
Make	BMW X2 xDrive 25e
Mileage	159660
First registration	10/11/2022
client availability date	06/02/2026
inspectionDate	11/02/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






## DAMAGES

Damages	Type	Acceptable
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	N
12	Bumper Front // Smart Repair Large	N
83	Door Front Left // Painting	Y
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
180	Wing Rear Right // Smart Repair Small	Y
201	Rocker Panel Right // Smart Repair Medium	N
219	Door Front Right / Window / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
421	Seat Front Right // Repair	Y
540	Interior // Repair 1	N
554	Central Console // Replace Completely	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
684	Charger Cable //	N
840	Interior Cleaning // Large	N

## Damage Pictures





Damage within Renta-norm-



Door Front Left // Painting-scratch



Bumper Front // Smart Repair Large-scratch



Wheel Two Tone Front Left // Repair-scratch




Wheel Two Tone Rear Left // Repair-scratch



Central Console // Replace Completely-scratch




Wheel Two Tone Front Right // Repair-scratch



Seat Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Bumper Rear // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Smart Repair Small-dent



Interior Cleaning // Large-stain




Interior // Repair 1-worn



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Front Right / Window / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent



Wing Rear Right / Trim / Replace-scratch + dent



Door Rear Right / Trim / Replace-scratch