



BMW X2: 2BEH046			
Vinnumber:	WBAYN910705U37839	Versionname:	
First Registrationdate:	20/10/2021	Fiscalpower:	
Expertise Mileage:	93668	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2808
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Head-up Display			
Type of GPS storage	HD		
Limited Technical Inspection			
Tyres			
225/55/17/97 W			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R. Michelin: 5 mm
	Re.L.	Continental: 5 mm	Re.R. Continental: 5 mm
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			225/55 R 17 97 W
Tyre size FR			225/55 R 17 97 W
Tyre size RL			225/55 R 17 97 W
Tyre size RR			225/55 R 17 97 W
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			261
Tyre make FR			261
Tyre make RL			256
Tyre make RR			256
Assistance equipment			
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		
Total cost ex VAT			1067,04
Seat cover FR, Stain, Cleaning			28,43




Windscreen, Stone chip(s), Replace 546,57



Alloy rim FL, Scratch(es), Repair and paint (complete) 129,66



Wing FL, Dent(s), Paintless dent repair 93,06



Alloy rim RL, Scratch(es), Acceptable 0,00



Boot cover, Missing, Repair/replace (lump sum) 10,00



Bumper R, Scratch(es), Acceptable 0,00



Bumper moulding R, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 129,66





Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FR, Scratch(es), Repair and paint (complete)	129,66
--	--------

