



BMW X2: K088JR

Vinnnummer:	WBAYN910X05S42365	Versionname:	X2 xDrive 25eA 162kW
First Registrationdate:	11/01/2021	Fiscalpower:	
Expertise Mileage:	73257	Power Kw:	92
Bodytype:		Body colour:	Phytonicblau metallic
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Wheel-drive	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	838
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Lining leather
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors

Degree of wear

225/55/17/97 H				
Winter tyres:	Fr.L.	Bridgestone: 4,8 mm	Fr.R.	Bridgestone: 3,5 mm
	Re.L.	Bridgestone: 5,5 mm	Re.R.	Bridgestone: 5,2 mm
Tyre profile depth FL				4.8
Tyre profile depth FR				3.5
Tyre profile depth RL				5.5
Tyre profile depth RR				5.2
Tyre size FL				225/55 R 17 97 H
Tyre size FR				225/55 R 17 97 H
Tyre size RL				225/55 R 17 97 H
Tyre size RR				225/55 R 17 97 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	0

Door RL, Scratch(es), Polish



Wing FL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Outer door handle FR, Scratch(es), Repair and paint (complete)



Charging cable (fast), Missing, Replace



Tailgate / Boot, Scratch(es), Polish



Bodywork, Paint measurement, Acceptable

