

Inspection Protocol

BMW I4 M50 XDRIVE GRAN COUPÉ, 544HK, 2023

Vehicle information

License plate	SXZ87A	Inspected by	A.A.
Year model	2023	Date of inspection	2025-11-28
Manuf. year/month	2022-09	City	Björkvik
First day in traffic	2022-09	Keys	2
Colour	Blå	Service book	Elektronisk servicebok
Mileage	74 780 km	Latest service	2024-09-09
Fuel	El (EV)	Mileage at the latest service	51 070 km
Transmission	Automat	Summer tires	18" alu-fälg 8/8/8/8
Engine effect	400 kW	Winter tires	alu-fälg dubbat 7/6/6/7

Damages

Location	Damage	Comments	Costs excluding VAT
Bumper, Rear	Smart repair	Lastrepor	70 €
Door, Rear right	Smart repair	Dörrupslag	70 €
Door, Righ side mirror	Repa/Repor		60 €
Bumper, Front	Smart repair		70 €
Bonnet, Bonnet	Smart repair		70 €
Glass, Windshield	Stenskott/Spricka		-
Service, Not serviced	Missad service		370 €

Total excl. VAT 710 €

Images

[See all images in large format](#)



























Stötfångare Bak Smart repair Lastrepor 1 000 kr




Dörr Höger bak Smart repair Dörrupslag 1 000 kr



Dörr Höger backspegel Repa/Repor 800 kr



Stötfångare Fram Smart repair 1 000 kr



Motorhuv Motorhuv Smart repair 1 000 kr



Glas Vindruta Stenskott/Spricka

