



## BMW iX3: N018RZ

|                         |                          |                        |                                             |
|-------------------------|--------------------------|------------------------|---------------------------------------------|
| Vinnumber:              | <b>WBY7X41030S088710</b> | Versionname:           | <b>iX3 210kW / 80kWH Executive automaat</b> |
| First Registrationdate: | <b>22/12/2021</b>        | Fiscalpower:           |                                             |
| Expertise Mileage:      | <b>130540</b>            | Power Kw:              | <b>210</b>                                  |
| Bodytype:               |                          | Body colour            | <b>Phytonicblau metallic lak</b>            |
| Gearbox:                | <b>Automatic</b>         | Paint type             | <b>Metallic</b>                             |
| Transmission:           | <b>4 Wheel-drive</b>     | Type of rims (mounted) | <b>Aluminium</b>                            |
| Fueltype:               | <b>Electric</b>          | Parking lot            | <b>534</b>                                  |
| Number of seats         | <b>5</b>                 |                        |                                             |
| Type of rims (mounted)  | <b>Aluminium</b>         |                        |                                             |
| Maintenance needed      | <b>Yes</b>               |                        |                                             |

## Options

|                       |          |                            |
|-----------------------|----------|----------------------------|
| Number of keys total  | <b>2</b> | Telephone equipment        |
| GPS                   |          | Lining leather             |
| Autom climate control |          | Sun Roof electric          |
| Windows electric F    |          | Panoramic roof             |
| Radio multimedia      |          | Central consol F           |
|                       |          | Luggage cover              |
|                       |          | Headlights Xenon/LED/Laser |
|                       |          | Front parking sensors      |
|                       |          | Rear parking sensors       |
|                       |          | Hook                       |

## Tyres

| Location | Position | Measures                            | Depth  | Make        | Type   |
|----------|----------|-------------------------------------|--------|-------------|--------|
| Front    | Left     | 245 / 45 / 20 / 103 / W / Aluminium | 8,4 mm | Bridgestone | Summer |
|          | Right    | 245 / 45 / 20 / 103 / W / Aluminium | 8,9 mm | Bridgestone | Summer |
| Rear     | Left     | 275 / 40 / 20 / 106 / W / Aluminium | 7,4 mm | Bridgestone | Summer |
|          | Right    | 275 / 40 / 20 / 106 / W / Aluminium | 7,4 mm | Bridgestone | Summer |

## Assistance equipment

|                                          |          |
|------------------------------------------|----------|
| Number of charging cables (normal)       | <b>1</b> |
| Number of charging cables (rapid charge) | <b>1</b> |

## Service, Maintenance, Execute



## Wing RL, Scratch(es), Repair and paint (complete)





Door RL, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Door RR, Bad repair, Repair and paint (complete)



Outer door handle FR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Check

