



MERCEDES-BENZ SLK-Klasse

SLK 350 7G-TRONIC

VIN NO WDB1714581F207763
Registration Number 581F207763



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-03-01	5	2	186014 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2009-04-01	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250924145757
Inspection Date / Place	2025-09-24 / BCA Heidenheim	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	3498
Engine Size	3.5	No of Doors	2
Body Type	Roadster	Drive Train	Rear
Seat Colour		No of Seats	2
Seat Covering Name	Schwarz	Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	209
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Alloys wheels	Bluetooth telephone interface	Enhanced speaker system
Front parking sensors	Remote adjusting wing mirrors	Satellite navigation	Xenon headlamps
Electrically folding wing mirrors	Radio	Airbag Status	Anti-lock braking
Cruise control	Front fog lamps	Headlamp wash/wipe	Remote central locking
Stability control	CD - multichanger	Leather steering wheel	Rear parking sensors


Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Enhanced Speaker System	harman/kardon	Seat Heating	Front


Wheels & Tyres

Left Front Tyre Depth	5	Right Front Tyre Depth	5
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

19 Schäden



7 Schäden

6/14 - Report Number P20250924145757

13	Rim / Front Left	Out of Bodywork / Scratch
14	Front Light / Front Left	Glass Break
15	Grille / Front	Paint / Scratch / Scuff
16	Front Light / Front Right	Glass Break
17	Rim / Front Right	Out of Bodywork / Scratch
18	Rim / Front Right	Out of Bodywork / Scratch
19	Rim / Front Right	Out of Bodywork / Scratch
20	Door / Front Right	Bodywork / Dent / Dent
21	Rim / Back Right	Out of Bodywork / Scratch
22	Rear Window / Back	Glass Break
23	Bumper / Back	Paint / Scratch / Scuff
24	Tailgate	Paint / Poor Previous Repair
25	Rear Window / Back	Glass Break
26	Door / Front Left	Bodywork / Dent / Dent



1. Seat / Front Left
Interior / Worn - out -



2. Aeration Grid / Front Center
Interior / Broken -



3. Dashboard / Front
Interior / Worn - out -



4. Dashboard / Front
Interior / Worn - out -



5. Dashboard / Front
Interior / Worn - out -



6. Dashboard / Front
Interior / Worn - out -



7. Seat / Front Right
Interior / Worn - out -



8. Hood
Paint / Poor Previous Repair -



9. Roof Molding / Right
Paint / Scratch / Scuff -



10. Door / Front Right
Paint / Poor Previous Repair -



11. Tailgate
Paint / Poor Previous Repair -



12. Fender / Front Left
Paint / Poor Previous Repair -



13. Rim / Front Left
Out of Bodywork / Scratch -



14. Front Light / Front Left
Glass Break -



15. Grille / Front
Paint / Scratch / Scuff -



16. Front Light / Front Right
Glass Break -




17. Rim / Front Right
Out of Bodywork / Scratch -



18. Rim / Front Right
Out of Bodywork / Scratch -



19. Rim / Front Right
Out of Bodywork / Scratch -



20. Door / Front Right
Bodywork / Dent / Dent -



21. Rim / Back Right
Out of Bodywork / Scratch -




22. Rear Window / Back
Glass Break -




23. Bumper / Back
Paint / Scratch / Scuff -



24. Tailgate
Paint / Poor Previous Repair -



25. Rear Window / Back
Glass Break -



26. Door / Front Left
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

AC / Heating System	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	❗	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)