



MERCEDES-BENZ C-Klasse

C 220 T CDI

VIN NO WDB2032081F584222
Registration Number 081F584222



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-04-01	3	2	464768 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2004-06-08	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250915083827
Inspection Date / Place	2025-09-15 / BCA Neuss	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	2148
Engine Size	2.1	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	180
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Alloys wheels	Cruise control	Front fog lamps
Remote central locking	Stability control	Leather steering wheel	Rear parking sensors
Airbag Status	Anti-lock braking	Diesel particulate filter	Remote adjusting wing mirrors
Roof rails	CD Player	Radio	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

30 Schäden



4 Schäden



1

Component		Damage	Comments
1	Roof Rack / Left	Out of Bodywork / Breakage	
2	Other	Paint / Poor Previous Repair	
3	Rim / Front Right	Out of Bodywork / Scratch	
4	Rim / Back Right	Out of Bodywork / Scratch	
5	Trunk Upholstery / Back	Interior / Broken	
6	Rim / Back Left	Out of Bodywork / Scratch	
7	Fender / Front Left	Bodywork / Dent / Dent	
8	Monogram/Emblem / Front Center	Missing Part	
9	Bumper / Front	Paint / Scratch / Scuff	
10	Bumper / Front	Paint / Chipping	
11	Bumper / Front	Paint / Scratch / Scuff	
12	Hood	Paint / Poor Previous Repair	


13	Door / Front Right	Bodywork / Dent / Dent
14	Door / Front Right	Paint / Chipping
15	Pillar / Front Right	Paint / Scratch / Scuff
16	Fender / Back Right	Paint / Corrosion
17	Roof Rack / Right	Out of Bodywork / Breakage
18	Roof Molding / Right	Out of Bodywork / Breakage
19	Fender / Back Right	Paint / Scratch / Scuff
20	Bumper / Back	Bodywork / Breakage / Crack
21	Tailgate	Bodywork / Dent / Dent
22	Tailgate	Paint / Corrosion
23	Fender / Back Left	Paint / Poor Previous Repair
24	Fender / Back Left	Paint / Corrosion
25	Back Light / Left	Bodywork / Breakage / Crack
26	Fender / Back Left	Paint / Scratch / Scuff
27	Door / Back Left	Paint / Corrosion
28	Door / Back Left	Paint / Scratch / Scuff
29	Pillar / Back Left	Paint / Scratch / Scuff
30	Door / Front Left	Paint / Scratch / Scuff
31	Panel Filling / Front Left	Interior / Broken
32	Steering Wheel / Front	Interior / Worn - out
33	Seat / Front Left	Interior / Ripped
34	Pillar / Front Left	Paint / Scratch / Scuff



1. Roof Rack / Left
Out of Bodywork / Breakage -



2.
Paint / Poor Previous Repair -



3. Rim / Front Right
Out of Bodywork / Scratch -




4. Rim / Back Right
Out of Bodywork / Scratch -




5. Trunk Upholstery / Back
Interior / Broken -




6. Rim / Back Left
Out of Bodywork / Scratch -




7. Fender / Front Left
Bodywork / Dent / Dent -



8. Monogram/Emblem / Front Center
Missing Part -



9. Bumper / Front
Paint / Scratch / Scuff -




10. Bumper / Front
Paint / Chipping -



11. Bumper / Front
Paint / Scratch / Scuff -




12. Hood
Paint / Poor Previous Repair -



13. Door / Front Right
Bodywork / Dent / Dent -




14. Door / Front Right
Paint / Chipping -




15. Pillar / Front Right
Paint / Scratch / Scuff -



16. Fender / Back Right
Paint / Corrosion -



17. Roof Rack / Right
Out of Bodywork / Breakage -



18. Roof Molding / Right
Out of Bodywork / Breakage -



19. Fender / Back Right
Paint / Scratch / Scuff -



20. Bumper / Back
Bodywork / Breakage / Crack -




21. Tailgate
Bodywork / Dent / Dent -




22. Tailgate
Paint / Corrosion -




23. Fender / Back Left
Paint / Poor Previous Repair -




24. Fender / Back Left
Paint / Corrosion -




25. Back Light / Left
Bodywork / Breakage / Crack -




26. Fender / Back Left
Paint / Scratch / Scuff -




27. Door / Back Left
Paint / Corrosion -



28. Door / Back Left
Paint / Scratch / Scuff -




29. Pillar / Back Left
Paint / Scratch / Scuff -



30. Door / Front Left
Paint / Scratch / Scuff -



31. Panel Filling / Front Left
Interior / Broken -



32. Steering Wheel / Front
Interior / Worn - out -



33. Seat / Front Left
Interior / Ripped -



34. Pillar / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Diesel Particulate Filter Light	✓
Airbag Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Parking Sensors / Cameras Functioning	!	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	NA
--------------	---	---------------	----

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Clutch			
Clutch Functioning		✔	
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)