



MERCEDES SPRINTER: 1SJL402

Vinnnumber:	WDB9062351N716313	Versionname:	319 CDI A3 DC 3.5T
First Registrationdate:	22/05/2017	Fiscalpower:	
Expertise Mileage:	237112	Power Kw:	140
Bodytype:		Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	Icv28
Fueltype:	Diesel		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Type of Tow bar:	Tow bar fixed
Steering wheel multifunctional:			
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining semi-artificial leather		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Degree of wear

235/65/16/113 R				
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/65 R 16 113 R
Tyre size FR				235/65 R 16 113 R
Tyre size RL				235/65 R 16 113 R
Tyre size RR				235/65 R 16 113 R
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	2685,67
--------------------	---------

Steering wheel, Worn, Acceptable:	0,00
-----------------------------------	------



Seat cover FL, Worn, Acceptable

0,00



Bumper F, Deformed / Strained, Replace

445,20



Bonnet, Dent(s) and scratch(es), Acceptable

0,00



Headlight L, Crack, Replace

471,13



Headlight R, Crack, Replace

471,13



Windscreen, Crack, Replace

0,00



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)

315,48



Door RL, Dent(s), Acceptable

0,00



Rear light R, Crack, Replace

163,98



Bumper R, Not original part, Acceptable

0,00



Door RR, Dent(s) and scratch(es), Repair and paint (complete)

325,87



Wing RR, Dent(s) and scratch(es), Acceptable

0,00



Bodywork, Not original part, Remove lettering

0,00



Roof, Not original part, Acceptable

0,00



Roof, Rust, Repair and paint (complete)

492,88

