

Vehicle details

VIN	WDB906633 1P625335	Brand	MERCEDES-BENZ	Maintenance date	-
Licence Plate	TK-08-0P	Model	Sprinter 316CDI 3665 3.5t 7G-Tronic 6 4d	Maintenance mileage	-
Registration date	05/09/2018	Year	2018	Exterior Color	Grey Metallic
Odometer	110 122 km	Engine size	2143	interior Color	Black
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	30/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
----------------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Continental 235/65/16 All seasons 9.0 mm		Continental 235/65/16 All seasons 8.5 mm	
Continental 235/65/16 All seasons 9.0 mm		Continental 235/65/16 All seasons 8.5 mm	

Exterior

1



●●●●

Part	Door
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

2



●●

Part	Wing
Position	Left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

3



●●

Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



●●

Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	-
Repair mode	Replace

5



●●●●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

6



●●●●●●●

Part	Door
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

7



●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8



●●

Part	Exterior door mirror shell
Position	Front left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

9



●●●

Part	Other bodywork
Position	-
Damages	Not conform
Severity	-
Repair mode	For info

buitenzijde nat

11



●●

Part	Door sill
Position	Left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

Interior damage

10



Part	Leather seat back
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info