



Mercedes-Benz Sprinter: V802NR

Vinnnummer:	WDB9066351P602913	Versionname:	Sprinter 311CDI 84kW GB 432/3500 7G-Tronic
First Registrationdate:	1/05/2018	Fiscalpower:	
Expertise Mileage:	60962	Power Kw:	84
Bodytype:		Body colour:	pool wit
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Steel
Fueltype:	Diesel	Parking lot:	1225
Number of seats:	2		
Type of rims (mounted):	Steel		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Windows electric F		Sliding door right-side
Radio multimedia		

Degree of wear

235/65/16/115 R				
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4,3 mm
	Re.L.	Goodyear: 4,8 mm	Re.R.	Goodyear: 6,7 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.3
Tyre profile depth RL				4.8
Tyre profile depth RR				6.7
Tyre size FL				235/65 R 16 115 R
Tyre size FR				235/65 R 16 115 R
Tyre size RL				235/65 R 16 115 R
Tyre size RR				235/65 R 16 115 R
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Radio, Not functioning (well), Replace



Portable GPS, Not functioning (well), Replace



Backrest cover FL, Worn, Replace



Interior, Stain, Cleaning



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Side bar L, Scratch(es), Replace



D-pillar left, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RL, Dent(s), Repair and paint (complete)



Windscreen, Scratch(es), Replace



Bumper F, Dent(s) and scratch(es), Replace





Sliding door R, Dent(s), Repair and paint (complete)



Wing FR, Dent(s), Repair and paint (complete)



Mirror side repeater R, Scratch(es), Replace



Door FR, Dent(s), Repair and paint (complete)



Side bar R, Deformed / Strained, Replace



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Door catch RR, Broken, Replace



Bull bar R, Dent(s), Replace



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, Chemical polution, Polish

