



MERCEDES-BENZ M-Klasse

ML 350 4MATIC (BlueEFFICIENCY) 7G-TRONIC

VIN NO WDC1660571A007638
Registration Number 571A007638



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-10-01	3	2	223732 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2011-11-30	Germany

Inspection Report Summary


Customer	BCA Online	Report Number	P20250819093844
Inspection Date / Place	2025-08-19 / BCA Heidenheim	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Black	Engine Size (cc)	3498
Engine Size	3.5	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Beige	Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	199
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tow ball	Alloys wheels	Cruise control	Remote adjusting wing mirrors
Roof rails	Split folding rear seats	Sunroof	Electrically adjustable seats
Electrictailgate	Privacy glass	Rear DVD system	Airbag Status
Anti-lock braking	Front parking sensors	Remote central locking	Satellite navigation
Stability control	CD Player	Electrically folding wing mirrors	Leather steering wheel
Radio	Rear parking sensors		

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front and Rear
Sunroof Type	Tilt/Slide Glass		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	3	Extra Wheel - 2 Tyre Depth	3
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4

Cosmetic Damage

17 Schäden



0 Schäden



Component		Damage	Comments
1	Rim / Front Left	Out of Bodywork / Scratch	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Fender / Front Right	Paint / Scratch / Scuff	
4	Hood	Paint / Scratch / Scuff	
5	Door / Front Right	Bodywork / Dent / Dent	
6	Door / Front Right	Bodywork / Dent / Dent	
7	Side Panel / Back Right	Bodywork / Dent / Dent	
8	Bumper / Back	Bodywork / Breakage / Hole	
9	Back Light / Left	Glass Break	
10	Tailgate	Bodywork / Dent / Dent	
11	Tailgate	Bodywork / Dent / Dent	
12	Door / Front Left	Bodywork / Dent / Dent	

13	Door / Front Left	Bodywork / Dent / Dent
14	Door / Back Left	Bodywork / Dent / Dent
15	Side Panel / Back Left	Bodywork / Dent / Dent
16	Door / Back Left	Bodywork / Dent / Dent
17	Roof	Paint / Scratch / Scuff




1. Rim / Front Left
Out of Bodywork / Scratch -




2. Bumper / Front
Paint / Scratch / Scuff -




3. Fender / Front Right
Paint / Scratch / Scuff -



4. Hood
Paint / Scratch / Scuff -



5. Door / Front Right
Bodywork / Dent / Dent -



6. Door / Front Right
Bodywork / Dent / Dent -




7. Side Panel / Back Right
Bodywork / Dent / Dent -




8. Bumper / Back
Bodywork / Breakage / Hole -




9. Back Light / Left
Glass Break -




10. Tailgate
Bodywork / Dent / Dent -




11. Tailgate
Bodywork / Dent / Dent -




12. Door / Front Left
Bodywork / Dent / Dent -




13. Door / Front Left
Bodywork / Dent / Dent -



14. Door / Back Left
Bodywork / Dent / Dent -



15. Side Panel / Back Left
Bodywork / Dent / Dent -



16. Door / Back Left
Bodywork / Dent / Dent -



17. Roof
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	!
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓		

Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓
Main & Spare Keys Functioning	✓		

Engine

Engine Status / EML	✓	Engine Starts	✓
---------------------	---	---------------	---

Gearbox

Gear Box	✓
----------	---

Levels

Coolant Fluid	✓	Brakes Fluid	✓
---------------	---	--------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly 

Engine

Engine Noise  Fume Quantity 

Power Loss 

General

Test Driven Status Not Performed

Brake

Brake System Anomaly 

Gearbox

Automatic Shift 

-  No troubles detected, good condition or correct tests, according to vehicle age and mileage
-  Damages or malfunction detected that requires repairs by the buyer
-  Not applicable
-  Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)