



# MERCEDES-BENZ GLK-Klasse

## GLK 220 CDI DPF 4Matic BlueEFFICIENCY

### 7G-TRONIC



VIN NO WDC2049841F711786  
Registration Number 841F711786

MOT Date

2026-07-01

Last Service

2021-09-10

Number of Owners

3

Last Service Mileage

173826

Number of Keys

2

First Registration Date

2011-06-03

Odometer Reading

214149 km

Country First Registered

Germany

## Inspection Report Summary


Customer	BCA Online	Report Number	P20250930102050
Inspection Date / Place	2025-09-30 / BCA Oberndorf	Cosmetic Grade	4

## Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	2143
Engine Size	2.1	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	159
Gearbox Type	Automatic		

## Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			








## Vehicle Remarketing Imagery

[Click Here For Larger Images](#)



## Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Cruise control
Front fog lamps	Remote adjusting wing mirrors	Roof rails	Stability control
Central locking	Radio	Tow ball	Alloys wheels
Bluetooth telephone interface	Diesel particulate filter	Front parking sensors	Remote central locking
Split folding rear seats	CD Player	Electric tailgate	Rear parking sensors

## Equipment Details

Tow Ball Type	Detachable	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	19	Seat Heating	Front


## Wheels & Tyres

Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5




Cosmetic Damage

18 Schäden



1 Schäden



Component		Damage	Comments
1	Other	Paint / Scratch / Scuff	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Hood	Bodywork / Dent / Dent	
4	Fender / Front Left	Paint / Scratch / Line	
5	Mirror / Front Left	Paint / Scratch / Line	
6	Door / Front Left	Bodywork / Dent / Dent	
7	Fender / Back Left	Paint / Scratch / Line	
8	Bumper / Back	Paint / Scratch / Scuff	
9	Bumper / Back	Paint / Scratch / Scuff	
10	Tailgate	Paint / Scratch / Line	
11	Luggage Space Cover / Back	Interior / Not Working	
12	Protective bar	Paint / Scratch / Scuff	

13	Fender / Back Right	Paint / Scratch / Line
14	Rim / Back Right	Paint / Stone Chip
15	Door / Front Right	Bodywork / Dent / Dent
16	Fender / Front Right	Bodywork / Dent / Dent
17	Rim / Front Right	Paint / Stone Chip



1.  
Paint / Scratch / Scuff -



2. Bumper / Front  
Paint / Scratch / Scuff -




3. Hood  
Bodywork / Dent / Dent -



4. Fender / Front Left  
Paint / Scratch / Line -



5. Mirror / Front Left  
Paint / Scratch / Line -



6. Door / Front Left  
Bodywork / Dent / Dent -






7. Fender / Back Left  
Paint / Scratch / Line -



8. Bumper / Back  
Paint / Scratch / Scuff -



9. Bumper / Back  
Paint / Scratch / Scuff -



10. Tailgate  
Paint / Scratch / Line -



11. Luggage Space Cover / Back  
Interior / Not Working -



12. Protective bar  
Paint / Scratch / Scuff -






13. Fender / Back Right  
Paint / Scratch / Line -



14. Rim / Back Right  
Paint / Stone Chip -



15. Door / Front Right  
Bodywork / Dent / Dent -



16. Fender / Front Right  
Bodywork / Dent / Dent -



17. Rim / Front Right  
Paint / Stone Chip -

## Mechanical Condition

### Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓

### Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓
Other Equipments	✓		

### Engine

Engine Status / EML	✓	Engine Leak Visible	❗
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---



Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

General

Test Driven Status Not Performed

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)