



MERCEDES Classe GLK-204 Diesel
GLK 220 cdi Premium B.E. 4matic auto '11

VIN NO WDC2049841F868254
Registration Number EL872YA



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-10-23	-	-	248352 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2012-04-23	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250918123841
Inspection Date / Place	2025-09-18 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	White	Engine Size (cc)	2143
Engine Size	2.1	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Leather
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Rear parking sensors	Digital Radio	Front parking sensors
Volante multifuncion	Remote adjusting wing mirrors	Cruise control	Trip Computer
Stability control	Power assisted steering	Alloys wheels	Electrically folding wing mirrors
Satellite navigation	Parcel Shef	Remote central locking	Traction control
Tyre Mobility Kit			


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	PIRELLI PIRELLI-SCORPION VERDE	235/50//R19 - 99V / 3 mm
	PIRELLI PIRELLI-SCORPION VERDE	235/50//R19 - 99V / 3 mm
	PIRELLI PIRELLI-SCORPION VERDE	255/45//R19 - 100V / 4 mm
	PIRELLI PIRELLI-SCORPION VERDE	255/45//R19 - 100V / 4 mm

Cosmetic Damage

21 Danni



6 Danni




Component		Damage	Comments
1	Window Switch / Front Left	Interior / Worn - out	
2	Cabin	Interior / Dirty	
3	Cabin	Interior / Dirty	
4	Cabin	Interior / Dirty	
5	Tailgate Upholstery / Back	Interior / Scratched	
6	Rim / Front Right	Out of Bodywork / Scratch	
7	Fender / Front Right	Paint / Chipping	
8	Door / Front Right	Bodywork / Poor Previous Repair	
9	Mirror Shell / Front Right	Paint / Scratch / Line	
10	Bumper / Front	Bodywork / Dent	
11	Hood	Bodywork / Dent	
12	Fender / Front Left	Bodywork / Dent	

13	Rim / Front Left	Out of Bodywork / Scratch
14	Bumper / Front	Bodywork / Dent
15	Door / Front Left	Bodywork / Poor Previous Repair
16	Rocker Panel / Center Left	Paint / Scratch / Line
17	Door / Back Left	Bodywork / Dent
18	Rim / Back Left	Out of Bodywork / Scratch
19	Fender / Back Left	Bodywork / Dent
20	Bumper / Back	Bodywork / Dent
21	Fog Light / Back Right	Glass Break
22	Rim / Back Right	Out of Bodywork / Scratch
23	Fender / Back Right	Bodywork / Dent
24	Door / Back Right	Paint / Scratch / Line
25	Rocker Panel / Center Right	Paint / Scratch / Line
26	Windshield / Front	Glass Break / Impact
27	Seat / Front Left	Interior / Worn - out



1. Window Switch / Front Left
Interior / Worn - out -



2. Cabin
Interior / Dirty -



3. Cabin
Interior / Dirty -



4. Cabin
Interior / Dirty -



5. Tailgate Upholstery / Back
Interior / Scratched -



6. Rim / Front Right
Out of Bodywork / Scratch -



7. Fender / Front Right
Paint / Chipping -




8. Door / Front Right
Bodywork / Poor Previous Repair -



9. Mirror Shell / Front Right
Paint / Scratch / Line -



10. Bumper / Front
Bodywork / Dent -



11. Hood
Bodywork / Dent -



12. Fender / Front Left
Bodywork / Dent -




13. Rim / Front Left
Out of Bodywork / Scratch -




14. Bumper / Front
Bodywork / Dent -



15. Door / Front Left
Bodywork / Poor Previous Repair -




16. Rocker Panel / Center Left
Paint / Scratch / Line -



17. Door / Back Left
Bodywork / Dent -



18. Rim / Back Left
Out of Bodywork / Scratch -



19. Fender / Back Left
Bodywork / Dent -




20. Bumper / Back
Bodywork / Dent -



21. Fog Light / Back Right
Glass Break -



22. Rim / Back Right
Out of Bodywork / Scratch -



23. Fender / Back Right
Bodywork / Dent -



24. Door / Back Right
Paint / Scratch / Line -



25. Rocker Panel / Center Right
Paint / Scratch / Line -



26. Windshield / Front
Glass Break / Impact -



27. Seat / Front Left
Interior / Worn - out -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
AC / Heating System	✓	Other Equipments	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

Not tested