



MERCEDES CLASSE CLA
Classe CLA 200 d 7-G DCT Sensation

VIN NO WDD1173081N555827
Registration Number ES629DF



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	2	106636 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2017-11-21	-

Inspection Report Summary

Customer	BCAauto Encheres	Report Number	P20250917085917
Inspection Date / Place	2025-09-17 / BCA LAUTERBOURG	Cosmetic Grade	4


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Auto clutch
Colour	Black	Engine Size (cc)	2143
Engine Size	2.1	No of Doors	4
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	105

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			





Equipment

Central locking	Radio	Cruise control	Satellite navigation
Electrically folding wing mirrors	Alloys wheels	Power assisted steering	

Equipment Details


Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Wheels & Tyres


Left Rear Tyre Depth	7	Left Front Tyre Depth	5
Right Rear Tyre Depth	7	Right Front Tyre Depth	5

Cosmetic Damage

27 Dommages



3 Dommages



Component		Damage	Comments
1	Window Switch / Front Left	Interior / Worn - out	
2	Seat Cushion / Back Right	Interior / Stained	
3	Seat Cushion / Front Right	Interior / Dirty	
4	Mirror Shell / Front Right	Paint / Scratch / Line	
5	Windshield / Front	Glass Break / Impact	
6	Rim	Out of Bodywork / Scratch	
7	Fender / Front Right	Paint / Scratch / Line	
8	Corner Bumper / Front Right	Paint / Scratch / Line	
9	Hood	Paint / Chipping	
10	Corner Bumper / Front Left	Paint / Chipping	
11	Rim	Out of Bodywork / Scratch	
12	Fender / Front Left	Paint / Chipping	

13	Rocker Panel / Center Left	Paint / Scratch / Line
14	Door / Front Left	Paint / Chipping
15	Roof	Bodywork / Dent / Dent
16	Door Handle / Back Left	Paint / Scratch / Line
17	Rim	Out of Bodywork / Scratch
18	Fender / Back Left	Paint / Scratch / Line
19	Corner Bumper / Back Left	Paint / Scratch / Line
20	Tailgate	Bodywork / Dent / Deformation
21	Corner Bumper / Back Right	Bodywork / Breakage / Crack
22	Bumper / Back	Paint / Scratch / Line
23	Cant Rail / Right	Bodywork / Dent / Deformation
24	Rim Brake pads	Out of Bodywork / Scratch
25	Fender / Back Right	Paint / Scratch / Line
26	Door / Back Right	Paint / Scratch / Line
27	Cant Rail / Right	Bodywork / Dent / Deformation
28	Rocker Panel / Center Right	Paint / Scratch / Line
29	Door / Back Right	Bodywork / Dent / Deformation
30	Door / Front Right	Paint / Chipping



1. Window Switch / Front Left
Interior / Worn - out -



2. Seat Cushion / Back Right
Interior / Stained -



3. Seat Cushion / Front Right
Interior / Dirty -




4. Mirror Shell / Front Right
Paint / Scratch / Line -



5. Windshield / Front
Glass Break / Impact -



6. Rim
Out of Bodywork / Scratch -



7. Fender / Front Right
Paint / Scratch / Line -



8. Corner Bumper / Front Right
Paint / Scratch / Line -



9. Hood
Paint / Chipping -



10. Corner Bumper / Front Left
Paint / Chipping -




11. Rim
Out of Bodywork / Scratch -



12. Fender / Front Left
Paint / Chipping -



13. Rocker Panel / Center Left
Paint / Scratch / Line -



14. Door / Front Left
Paint / Chipping -




15. Roof
Bodywork / Dent / Dent -



16. Door Handle / Back Left
Paint / Scratch / Line -




17. Rim
Out of Bodywork / Scratch -



18. Fender / Back Left
Paint / Scratch / Line -



19. Corner Bumper / Back Left
Paint / Scratch / Line -



20. Tailgate
Bodywork / Dent / Deformation -



21. Corner Bumper / Back Right
Bodywork / Breakage / Crack -



22. Bumper / Back
Paint / Scratch / Line -



23. Cant Rail / Right
Bodywork / Dent / Deformation -




24. Rim Brake pads
Out of Bodywork / Scratch -




25. Fender / Back Right
Paint / Scratch / Line -




26. Door / Back Right
Paint / Scratch / Line -




27. Cant Rail / Right
Bodywork / Dent / Deformation -



28. Rocker Panel / Center Right
Paint / Scratch / Line -



29. Door / Back Right
Bodywork / Dent / Deformation -



30. Door / Front Right
Paint / Chipping -

Mechanical Condition

Levels

Coolant Fluid - Condition	✓	Oil - Condition	✓
Level - Oil	✓	Coolant Fluid	✓
Brakes Fluid	✓		

Engine

Cross Member	NA	Serpentine Belt	✓
Control Liquid Leak	✓		

Tyres

Presence Anti-Theft Lock Nut	✓
------------------------------	---

Dashboard Lights

ABS Warning Light	✓	Diesel Particulate Filter Light	✓
ESP Fault/Traction Control Malfunction Light	✓	4WD Light	NA
Dashboard Working	✓	Engine Light	!
Oil Pressure Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Level - Fuel / Battery	40
Transmission Warning Light	NA	Service Light	!
Steering Fluid Level	NA		

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	NA	Dump / Trail / Tail Gate Lift	NA
Central Locking	✓	Audio Equipment	✓
Navigation System	✓	AC / Heating System	✓
Parking Sensors / Cameras Functioning	✓		

Hybrid/EV

Charge Port Condition	NA	Charge lead 1 condition /Charge lead 2 condition	NA
-----------------------	----	--	----

Test Drive Inspection

Test Drive			
Engine functioning	✓	Engine / Aux Belt / Pulley Noise	✓
Vehicle Starts	✓	Steering Noise/Gripping	✓
Engine Power	!	Smoke Quantity	✓
Transmission	✓	Clutch Functioning	NA
Steering	✓	Brakes Functioning	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.