



MERCEDES-BENZ A-Klasse

A 170 CDI L

VIN NO WDD1681091K001305
Registration Number 091K001305



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250828092429
Inspection Date / Place	2025-08-28 / Dello Lübeck	Cosmetic Grade	9

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1689
Engine Size	1.7	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Blau/Grau	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tow ball	Alloys wheels	Auxiliary Socket	Remote adjusting wing mirrors
Split folding rear seats	Radio	Rear parking sensors	Airbag Status
Anti-lock braking	Cruise control	Remote central locking	Stability control
Rain sensitive windscreen wipers			

Equipment Details


Tow Ball Type	Detachable	Air Conditioning	Yes
Alloy Wheel Size	15	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

21 Schäden




2 Schäden




Component		Damage	Comments
1	Door / Front Left	Bodywork / Dent / Dent	
2	Door / Back Left	Paint / Poor Previous Repair	
3	Other	Paint / Poor Previous Repair	
4	Hood	Paint / Chemical Damage	
5	Hood	Bodywork / Dent / Dent	
6	Hood	Paint / Corrosion	
7	Hood	Paint / Corrosion	
8	Bumper / Front	Paint / Scratch / Scuff	
9	Other	Paint / Scratch / Scuff	
10	Bumper / Front	Paint / Scratch / Scuff	
11	Antenna Rod	Missing Part	
12	Roof Molding / Right	Out of Bodywork / Breakage	

13	Wheel Arch / Back Right	Paint / Corrosion
14	Bumper / Back	Paint / Scratch / Scuff
15	Side Panel / Back Right	Paint / Corrosion
16	Wheel Arch / Back Left	Paint / Corrosion
17	Side Panel / Back Left	Paint / Scratch / Scuff
18	Door Side Molding / Front Left	Bodywork / Breakage / Crack
19	Window Cover / Front Left	Bodywork / Breakage / Crack
20	Window Cover / Front Right	Bodywork / Breakage
21	Seat / Front Left	Interior / Ripped
22	Steering Wheel / Front	Interior / Worn - out
23	Side Panel / Back Left	Paint / Corrosion



1. Door / Front Left
Bodywork / Dent / Dent -



2. Door / Back Left
Paint / Poor Previous Repair -



3.
Paint / Poor Previous Repair -



4. Hood
Paint / Chemical Damage -



5. Hood
Bodywork / Dent / Dent -



6. Hood
Paint / Corrosion -



7. Hood
Paint / Corrosion -



8. Bumper / Front
Paint / Scratch / Scuff -



9.
Paint / Scratch / Scuff -



10. Bumper / Front
Paint / Scratch / Scuff -



11. Antenna Rod
Missing Part -



12. Roof Molding / Right
Out of Bodywork / Breakage -



13. Wheel Arch / Back Right
Paint / Corrosion -



14. Bumper / Back
Paint / Scratch / Scuff -




15. Side Panel / Back Right
Paint / Corrosion -




16. Wheel Arch / Back Left
Paint / Corrosion -



17. Side Panel / Back Left
Paint / Scratch / Scuff -




18. Door Side Molding / Front Left
Bodywork / Breakage / Crack -



19. Window Cover / Front Left
Bodywork / Breakage / Crack -



20. Window Cover / Front Right
Bodywork / Breakage -



21. Seat / Front Left
Interior / Ripped -



22. Steering Wheel / Front
Interior / Worn - out -



23. Side Panel / Back Left
Paint / Corrosion -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	⚠
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓
Other Equipments	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly 

Engine

Engine Noise	NA	The Gears Scratch / Skip / Abnormal Operation	NA
Fume Quantity		Power Loss	

Brake

Brake System Anomaly NA

General

Test Driven Status NA

-  No troubles detected, good condition or correct tests, according to vehicle age and mileage
-  Damages or malfunction detected that requires repairs by the buyer
-  Not applicable
-  Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)