



MERCEDES-BENZ A-Klasse A 150 Autotronic

VIN NO WDD1690311J133386

Registration Number 311J133386



MOT Date

2027-03-01

Last Service



Number of Owners

4

Last Service Mileage



Number of Keys

1

First Registration Date

2005-04-21

Odometer Reading

161523 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250915084115
Inspection Date / Place	2025-09-15 / BCA Neuss	Cosmetic Grade	9


Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Automatic
Colour	Silver	Engine Size (cc)	1498
Engine Size	1.5	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	159

Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Remote adjusting wing mirrors	CD Player
Alloys wheels	Front fog lamps	Remote central locking	Radio

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	15
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

51 Schäden



2 Schäden



Component		Damage	Comments
1	Rocker Panel / Center Left	Paint / Scratch / Scuff	
2	B Pillar / Center Left	Paint / Scratch / Scuff	
3	Pillar / Back Left	Paint / Scratch / Scuff	
4	Pillar / Back Right	Paint / Scratch / Scuff	
5	Rocker Panel / Center Right	Paint / Scratch / Scuff	
6	Seat / Front Right	Interior / Broken	
7	Seat / Front Left	Interior / Broken	
8	Door / Back Left	Paint / Poor Previous Repair	
9	Fender / Back Left	Paint / Poor Previous Repair	
10	Hood	Bodywork / Dent / Dent	
11	Hood	Bodywork / Dent / Dent	
12	Hood	Bodywork / Dent / Dent	

13	Hood	Bodywork / Dent / Dent
14	Corner Bumper / Front Right	Paint / Scratch / Scuff
15	Corner Bumper / Front Right	Bodywork / Breakage
16	Corner Bumper / Front Right	Bodywork / Breakage
17	Bumper / Front	Paint / Scratch / Scuff
18	Corner Bumper / Front Left	Paint / Scratch / Scuff
19	Corner Bumper / Front Left	Paint / Scratch / Scuff
20	Rim / Front Left	Out of Bodywork / Scratch
21	Corner Bumper / Front Left	Bodywork / Breakage
22	Fender / Front Left	Bodywork / Dent / Dent
23	Door / Front Left	Bodywork / Dent / Dent
24	Door / Front Left	Bodywork / Dent / Dent
25	Door / Front Left	Paint / Scratch / Scuff
26	Door / Back Left	Bodywork / Dent / Dent
27	Door / Back Left	Bodywork / Dent / Dent
28	Door / Back Left	Bodywork / Dent / Dent
29	Rim / Back Left	Out of Bodywork / Scratch
30	Fender / Back Left	Bodywork / Dent / Dent
31	Fender / Back Left	Paint / Scratch / Scuff
32	Roof	Paint / Chipping
33	Corner Bumper / Back Left	Paint / Scratch / Scuff
34	Bumper / Back	Paint / Scratch / Scuff
35	Tailgate	Bodywork / Dent / Dent
36	Corner Bumper / Back Right	Bodywork / Breakage
37	Fender / Back Right	Bodywork / Dent / Dent
38	Roof	Bodywork / Dent / Dent
39	Roof	Bodywork / Dent / Dent
40	Roof	Bodywork / Dent / Dent
41	Roof	Bodywork / Dent / Dent


42	Roof	Bodywork / Dent / Dent
43	Roof	Bodywork / Dent / Dent
44	Rim / Back Right	Out of Bodywork / Scratch
45	Side Panel / Back Right	Paint / Scratch / Scuff
46	Door / Front Left	Paint / Poor Previous Repair
47	Door / Back Left	Paint / Scratch / Scuff
48	Door / Back Right	Bodywork / Dent / Dent
49	Door / Back Right	Bodywork / Dent / Dent
50	Door / Back Right	Paint / Scratch / Scuff
51	Door / Front Right	Bodywork / Dent / Dent
52	Rocker Panel / Center Right	Paint / Scratch / Scuff
53	Rim	Out of Bodywork / Scratch



1. Rocker Panel / Center Left
Paint / Scratch / Scuff -




2. B Pillar / Center Left
Paint / Scratch / Scuff -




3. Pillar / Back Left
Paint / Scratch / Scuff -



4. Pillar / Back Right
Paint / Scratch / Scuff -



5. Rocker Panel / Center Right
Paint / Scratch / Scuff -



6. Seat / Front Right
Interior / Broken -



7. Seat / Front Left
Interior / Broken -




8. Door / Back Left
Paint / Poor Previous Repair -



9. Fender / Back Left
Paint / Poor Previous Repair -




10. Hood
Bodywork / Dent / Dent -




11. Hood
Bodywork / Dent / Dent -



12. Hood
Bodywork / Dent / Dent -



13. Hood
Bodywork / Dent / Dent -



14. Corner Bumper / Front Right
Paint / Scratch / Scuff -



15. Corner Bumper / Front Right
Bodywork / Breakage -




16. Corner Bumper / Front Right
Bodywork / Breakage -



17. Bumper / Front
Paint / Scratch / Scuff -




18. Corner Bumper / Front Left
Paint / Scratch / Scuff -




19. Corner Bumper / Front Left
Paint / Scratch / Scuff -



20. Rim / Front Left
Out of Bodywork / Scratch -




21. Corner Bumper / Front Left
Bodywork / Breakage -



22. Fender / Front Left
Bodywork / Dent / Dent -




23. Door / Front Left
Bodywork / Dent / Dent -




24. Door / Front Left
Bodywork / Dent / Dent -




25. Door / Front Left
Paint / Scratch / Scuff -



26. Door / Back Left
Bodywork / Dent / Dent -




27. Door / Back Left
Bodywork / Dent / Dent -



28. Door / Back Left
Bodywork / Dent / Dent -



29. Rim / Back Left
Out of Bodywork / Scratch -




30. Fender / Back Left
Bodywork / Dent / Dent -




31. Fender / Back Left
Paint / Scratch / Scuff -




32. Roof
Paint / Chipping -




33. Corner Bumper / Back Left
Paint / Scratch / Scuff -




34. Bumper / Back
Paint / Scratch / Scuff -



35. Tailgate
Bodywork / Dent / Dent -



36. Corner Bumper / Back Right
Bodywork / Breakage -




37. Fender / Back Right
Bodywork / Dent / Dent -




38. Roof
Bodywork / Dent / Dent -




39. Roof
Bodywork / Dent / Dent -




40. Roof
Bodywork / Dent / Dent -



41. Roof
Bodywork / Dent / Dent -




42. Roof
Bodywork / Dent / Dent -



43. Roof
Bodywork / Dent / Dent -




44. Rim / Back Right
Out of Bodywork / Scratch -




45. Side Panel / Back Right
Paint / Scratch / Scuff -




46. Door / Front Left
Paint / Poor Previous Repair -



47. Door / Back Left
Paint / Scratch / Scuff -




48. Door / Back Right
Bodywork / Dent / Dent -



49. Door / Back Right
Bodywork / Dent / Dent -



50. Door / Back Right
Paint / Scratch / Scuff -



51. Door / Front Right
Bodywork / Dent / Dent -



52. Rocker Panel / Center Right
Paint / Scratch / Scuff -



53. Rim
Out of Bodywork / Scratch -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Audio Equipment	✓	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)