



MERCEDES-BENZ A-Klasse

A 150

VIN NO WDD1690311J702362
Registration Number 311J702362



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-12-01	3	2	168659 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2008-12-08	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250922094147
Inspection Date / Place	2025-09-22 / ARS Altmann AG Riedstadt	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1498
Engine Size	1.5	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	148
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Alloys wheels	Bluetooth telephone interface	Remote adjusting wing mirrors
Stability control	Electrically folding wing mirrors	Radio	Airbag Status
Anti-lock braking	Front parking sensors	Remote central locking	CD Player
Leather steering wheel	Rear parking sensors		


Equipment Details

Air Conditioning	Yes	Alloy Wheel Size	16
Seat Heating	Front		


Wheels & Tyres

Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

19 Schäden



2 Schäden

6/13 - Report Number P20250922094147


13	Fender / Back Right	Bodywork / Dent / Dent
14	Rim / Back Right	Out of Bodywork / Scratch
15	Pillar / Back Right	Paint / Scratch / Scuff
16	Door / Back Right	Bodywork / Dent / Dent
17	Door / Back Right	Paint / Scratch / Scuff
18	Door / Front Right	Paint / Scratch / Scuff
19	Rim / Front Right	Out of Bodywork / Scratch
20	Fender / Front Right	Paint / Scratch / Scuff
21	Fender / Front Left	Paint / Scratch / Scuff



1. Windshield / Front
Glass Break / Scratch / Scratch -




2. Hood
Paint / Scratch / Scuff -



3. Bumper / Front
Paint / Scratch / Scuff -




4. Rim / Front Left
Out of Bodywork / Scratch -




5. Panel Filling / Front Left
Interior / Scratched -




6. Seat / Front Left
Interior / Ripped -



7. Door / Back Left
Bodywork / Dent / Dent -



8. Door / Back Left
Bodywork / Dent / Dent -



9. Door Handle / Back Left
Bodywork / Breakage -




10. Bumper / Back
Bodywork / Breakage / Hole -



11. Rim / Back Left
Out of Bodywork / Scratch -



12. Rear Window / Back
Glass Break / Scratch / Scratch -




13. Fender / Back Right
Bodywork / Dent / Dent -




14. Rim / Back Right
Out of Bodywork / Scratch -



15. Pillar / Back Right
Paint / Scratch / Scuff -



16. Door / Back Right
Bodywork / Dent / Dent -




17. Door / Back Right
Paint / Scratch / Scuff -




18. Door / Front Right
Paint / Scratch / Scuff -



19. Rim / Front Right
Out of Bodywork / Scratch -



20. Fender / Front Right
Paint / Scratch / Scuff -



21. Fender / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Equipments Test

Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	AC / Heating System	✓
Other Equipments	✓	Main & Spare Keys Functioning	✓
Parking Sensors / Cameras Functioning	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)