



MERCEDES-BENZ A-Klasse
A 200 CDI (BlueEFFICIENCY)

VIN NO WDD1760011J203276
Registration Number 011J203276



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-01-01	2	2	191949 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-10-29	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250922134230
Inspection Date / Place	2025-09-23 / ARS Altmann AG Riedstadt	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1796
Engine Size	1.8	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	111
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Alloys wheels	Bi Xenon Headlamps	Diesel particulate filter
Front parking sensors	Heated wing mirrors	Remote central locking	Stability control
Distancewarningsystem	Leather steering wheel	Rear parking sensors	Airbag Status
Anti-lock braking	Bluetooth telephone interface	Fatiguewarningsystem	Headlamp wash/wipe
Remote adjusting wing mirrors	Satellite navigation	CD Player	Electrically folding wing mirrors
Radio			

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	16
Satellite Navigation	BeckerMap	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	7	Left Rear Tyre Depth	7

Cosmetic Damage


1 Schäden



0 Schäden



Component		Damage	Comments
1	Hood	Paint / Stone Chip	



1. Hood
Paint / Stone Chip -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Other Equipments	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓		
Clutch			
Clutch Functioning	✓		
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	✓		

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ☐ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)