



MERCEDES Classe A - W176 Diesel
A 180 d Premium my16

VIN NO WDD1760121J583489
Registration Number FH375DH



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-03-26	-	-	180777 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2017-01-31	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250918170832
Inspection Date / Place	2025-09-18 / BCA Lodi	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1461
Engine Size	1.5	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	103

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Alloys wheels	Satellite navigation	Volante multifuncion
Remote adjusting wing mirrors	Trip Computer	Power assisted steering	Digital Radio
Sunroof	Parcel Shef	Remote central locking	Stability control


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Four Seasons
	225/40//R18 - 92Y / 1 mm
	//R / 1 mm
	225/40//R18 - 92Y / 2 mm
	225/40//R18 - 92Y / 2 mm

Cosmetic Damage

20 Danni



7 Danni



Component	Damage	Comments
1 Dashboard / Front	Interior / Warning Light ON	
2 Seat / Front Right	Interior / Dirty	
3 Sunroof	Bodywork / Breakage	NON FUNZIONANTE
4 Seat / Front Left	Interior / Broken	
5 Floor Carpet	Interior / Burn	
6 Steering Wheel / Front	Interior / Worn - out	
7 Panel Filling / Front Left	Interior / Worn - out	
8 Dashboard / Front	Interior / Scratched	
9 Rim / Front Right	Out of Bodywork / Scratch	
10 Fender / Front Right	Bodywork / Poor Previous Repair	
11 Door / Front Right	Bodywork / Poor Previous Repair	
12 Bumper / Front	Paint / Chipping	

13	Hood	Bodywork / Poor Previous Repair
14	Windshield / Front	Glass Break / Scratch
15	Rim / Front Left	Out of Bodywork / Scratch
16	Door / Front Left	Paint / Scratch / Line
17	Door / Back Left	Bodywork / Dent
18	Rim / Back Left	Out of Bodywork / Scratch
19	Pillar / Front Left	Bodywork / Dent / Hail Area
20	Fender / Back Left	Bodywork / Dent / Hail Area
21	Bumper / Back	Bodywork / Dent
22	Roof	Bodywork / Dent / Hail Area
23	Rim / Back Right	Out of Bodywork / Scratch
24	Fender / Back Right	Bodywork / Poor Previous Repair
25	Pillar / Front Right	Bodywork / Poor Previous Repair
26	Door / Back Right	Paint / Chipping
27	Rocker Panel / Center Right	Paint / Scratch / Line




1. Dashboard / Front Interior / Warning Light ON -



2. Seat / Front Right Interior / Dirty -




3. Sunroof Bodywork / Breakage - NON FUNZIONANTE



4. Seat / Front Left Interior / Broken -



5. Floor Carpet Interior / Burn -



6. Steering Wheel / Front Interior / Worn - out -



7. Panel Filling / Front Left
Interior / Worn - out -



8. Dashboard / Front
Interior / Scratched -



9. Rim / Front Right
Out of Bodywork / Scratch -



10. Fender / Front Right
Bodywork / Poor Previous Repair -



11. Door / Front Right
Bodywork / Poor Previous Repair -



12. Bumper / Front
Paint / Chipping -



13. Hood
Bodywork / Poor Previous Repair -




14. Windshield / Front
Glass Break / Scratch -




15. Rim / Front Left
Out of Bodywork / Scratch -




16. Door / Front Left
Paint / Scratch / Line -



17. Door / Back Left
Bodywork / Dent -



18. Rim / Back Left
Out of Bodywork / Scratch -



19. Pillar / Front Left
Bodywork / Dent / Hail Area -



20. Fender / Back Left
Bodywork / Dent / Hail Area -



21. Bumper / Back
Bodywork / Dent -



22. Roof
Bodywork / Dent / Hail Area -




23. Rim / Back Right
Out of Bodywork / Scratch -



24. Fender / Back Right
Bodywork / Poor Previous Repair -



25. Pillar / Front Right
Bodywork / Poor Previous Repair -



26. Door / Back Right
Paint / Chipping -



27. Rocker Panel / Center Right
Paint / Scratch / Line -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			