



MERCEDES-BENZ A-Klasse

A 180 d 7G DCT

VIN NO WDD1760121J674924
Registration Number 121J674924



MOT Date

2026-07-01

Last Service



Number of Owners

3

Last Service Mileage



Number of Keys

2

First Registration Date

2017-08-29

Odometer Reading

64245 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250925100628
Inspection Date / Place	2025-09-25 / BCA Neuss	Cosmetic Grade	2

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1461
Engine Size	1.5	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	98
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

USB Socket	Alloys wheels	Bluetooth telephone interface	Diesel particulate filter
Remote adjusting wing mirrors	Satellite navigation	Leather steering wheel	Rain sensitive windscreen wipers
Airbag Status	Anti-lock braking	Cruise control	Front parking sensors
Remote central locking	Stability control	Radio	Rear parking sensors

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

2 Schäden




0 Schäden



Component		Damage	Comments
1	Fender / Back Left	Paint / Poor Previous Repair	
2	Rocker Panel / Center Right	Paint / Scratch / Scuff	



1. Fender / Back Left
Paint / Poor Previous Repair -



2. Rocker Panel / Center Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Main & Spare Keys Functioning	⚠
Parking Sensors / Cameras Functioning	✓		

Levels

Brakes Fluid	NA	Coolant Fluid	✓
--------------	----	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise Fume Quantity

Power Loss The Gears Scratch / Skip / Abnormal Operation

Brake

Brake System Anomaly

General

Test Driven Status

No troubles detected, good condition or correct tests, according to vehicle age and mileage

Damages or malfunction detected that requires repairs by the buyer

Not applicable

Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)