



MERCEDES-BENZ A-Klasse

A 180 (BlueEFFICIENCY)

VIN NO WDD1760421J284337
Registration Number 421J284337



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-08-01	2	2	28847 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2014-05-19	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250909144139
Inspection Date / Place	2025-09-09 / BCA Berlin	Cosmetic Grade	2




Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Grey	Engine Size (cc)	1595
Engine Size	1.6	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	127
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Alloys wheels	Remote adjusting wing mirrors	Reversing Camera
CD Player	Radio	Airbag Status	Anti-lock braking
Remote central locking	Stability control	Electrically folding wing mirrors	

Equipment Details

Air Conditioning	Yes	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres


Left Front Tyre Depth	6	Right Rear Tyre Depth	7
Left Rear Tyre Depth	6	Right Front Tyre Depth	7

Cosmetic Damage


	Component	Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	
2	Fender / Front Left	Bodywork / Dent / Dent	
3	Door / Front Left	Bodywork / Dent / Dent	



1. Bumper / Front
Paint / Scratch / Scuff -



2. Fender / Front Left
Bodywork / Dent / Dent -



3. Door / Front Left
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Equipments Test

Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓
Parking Sensors / Cameras Functioning	✓	Other Equipments	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
Clutch			
Clutch Functioning		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)