



MERCEDES-BENZ A-Klasse

A 180 7G-DCT

VIN NO WDD1760421J605890
Registration Number 421J605890



MOT Date

2027-05-01

Last Service



Number of Owners

3

Last Service Mileage



Number of Keys

2

First Registration Date

2017-03-28

Odometer Reading

127206 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250926110332
Inspection Date / Place	2025-09-26 / HARTMANN Compound-Professionals GmbH Dorfmark	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1595
Engine Size	1.6	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	127
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Airbag Status	Anti-lock braking	Cruise control
Remote adjusting wing mirrors	Reversing Camera	Leather steering wheel	Rear parking sensors
USB Socket	Alloys wheels	Bluetooth telephone interface	Front parking sensors
Remote central locking	Stability control	Radio	


Equipment Details

Air Conditioning	Yes	Alloy Wheel Size	16
Seat Heating	Front		


Wheels & Tyres

Right Front Tyre Depth	7	Left Front Tyre Depth	5
Right Rear Tyre Depth	7	Left Rear Tyre Depth	7

26 Damages




1 Damages

6/14 - Report Number P20250926110332

13	Rim / Back Right	Out of Bodywork / Scratch
14	Bumper / Back	Paint / Scratch / Scuff
15	Tailgate	Paint / Scratch / Scuff
16	Side Panel / Back Left	Paint / Scratch / Scuff
17	Rim / Back Left	Out of Bodywork / Scratch
18	Door / Back Left	Bodywork / Dent / Dent
19	Door / Back Left	Paint / Stone Chip
20	Door / Front Left	Paint / Scratch / Scuff
21	Door / Front Left	Paint / Scratch / Scuff
22	Door / Front Left	Paint / Scratch / Scuff
23	Wing Stick / Front Left	Bodywork / Dent / Dent
24	Hood	Paint / Scratch / Scuff
25	Rim / Front Left	Out of Bodywork / Scratch
26	Corner Bumper / Front Left	Paint / Scratch / Scuff
27	Panel Filling / Front Left	Interior / Dirty



1. Hood
Paint / Stone Chip -



2. Fender / Front Right
Paint / Stone Chip -



3. Rim / Front Right
Out of Bodywork / Scratch -



4. Mirror / Front Right
Paint / Scratch / Scuff -



5. Roof
Bodywork / Dent / Dent -




6. Door / Front Right
Paint / Scratch / Scuff -



7. Door / Back Right
Paint / Chipping -




8. Door / Back Right
Paint / Stone Chip -




9. Door / Back Right
Bodywork / Dent / Dent -



10. Door / Back Right
Bodywork / Dent / Dent -



11. Side Panel / Back Right
Bodywork / Dent / Dent -



12. Side Panel / Back Right
Bodywork / Dent / Dent -




13. Rim / Back Right
Out of Bodywork / Scratch -



14. Bumper / Back
Paint / Scratch / Scuff -




15. Tailgate
Paint / Scratch / Scuff -




16. Side Panel / Back Left
Paint / Scratch / Scuff -




17. Rim / Back Left
Out of Bodywork / Scratch -




18. Door / Back Left
Bodywork / Dent / Dent -




19. Door / Back Left
Paint / Stone Chip -



20. Door / Front Left
Paint / Scratch / Scuff -




21. Door / Front Left
Paint / Scratch / Scuff -



22. Door / Front Left
Paint / Scratch / Scuff -



23. Wing Stick / Front Left
Bodywork / Dent / Dent -



24. Hood
Paint / Scratch / Scuff -



25. Rim / Front Left
Out of Bodywork / Scratch -



26. Corner Bumper / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Engine			
Engine Leak Visible	✓	Engine Starts	✓
Engine Status / EML	✓		
Levels			
Coolant Fluid	✓	Brakes Fluid	✓
Equipments Test			
Central Locking	✓	Audio Equipment	✓
AC / Heating System	✓	Electric Windows	✓
Navigation System	✓		
Control Lights			
ABS Warning Light	✓	Oil Pressure Warning Light	✓
Airbag Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓

Test Drive Inspection

Engine			
Fume Quantity	✓	Engine Noise	✓
Power Loss	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
Brake			
Brake System Anomaly	✓		
Gearbox			
Automatic Shift	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

 *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)