



MERCEDES-BENZ A-Klasse  
A 250 4Matic 7G-DCT

VIN NO WDD1760461J162965  
Registration Number 461J162965



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-10-01	2	2	208517 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-08-13	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250925084851
Inspection Date / Place	2025-09-25 / BCA Berlin	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Grey	Engine Size (cc)	1991
Engine Size	2.0	No of Doors	5
Body Type	Sedan	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Alcantara/Leather
Charging Cables		NEDC CO2 Rating (q/km)	152
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Cruise control
Remote adjusting wing mirrors	Reversing Camera	Stability control	CD Player
Leather steering wheel	Rear parking sensors	USB Socket	Alloys wheels
Bluetooth telephone interface	Front parking sensors	Remote central locking	Split folding rear seats
Xenon headlamps	Electrically folding wing mirrors	Radio	

Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front


Wheels & Tyres

Extra Wheel - 1 Tyre Depth	6	Extra Wheel - 2 Tyre Depth	6
Extra Wheel - 3 Tyre Depth	6	Extra Wheel - 4 Tyre Depth	6
Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3




Cosmetic Damage

13 Schäden



7 Schäden



Component		Damage	Comments
1	Other	Interior / Loose	
2	Other	Interior / Loose	
3	Roof	Paint / Stone Chip	
4	Side Panel / Back Left	Bodywork / Dent / Dent	
5	Side Panel / Back Left	Bodywork / Dent / Dent	
6	Corner Bumper / Front Left	Paint / Scratch / Scuff	
7	Corner Bumper / Front Right	Paint / Scratch / Scuff	
8	Bumper / Front	Paint / Stone Chip	
9	Hood	Paint / Stone Chip	
10	Rim / Front Left	Out of Bodywork / Scratch	
11	Door / Front Left	Paint / Scratch / Line	
12	Door / Back Left	Paint / Scratch / Scuff	

13	Bumper / Back	Paint / Scratch / Scuff
14	Rim / Front Right	Paint / Corrosion
15	Fender / Front Right	Paint / Stone Chip
16	Door Step / Front Left	Interior / Holed
17	Seat / Front Left	Interior / Ripped
18	Tailgate Upholstery / Back	Interior / Scratched
19	Door Step / Back Right	Interior / Dented
20	Seat / Front Right	Interior / Holed



1.  
Interior / Loose -




2.  
Interior / Loose -



3. Roof  
Paint / Stone Chip -



4. Side Panel / Back Left  
Bodywork / Dent / Dent -



5. Side Panel / Back Left  
Bodywork / Dent / Dent -



6. Corner Bumper / Front Left  
Paint / Scratch / Scuff -





7. Corner Bumper / Front Right  
Paint / Scratch / Scuff -



8. Bumper / Front  
Paint / Stone Chip -




9. Hood  
Paint / Stone Chip -



10. Rim / Front Left  
Out of Bodywork / Scratch -



11. Door / Front Left  
Paint / Scratch / Line -



12. Door / Back Left  
Paint / Scratch / Scuff -







13. Bumper / Back  
Paint / Scratch / Scuff -




14. Rim / Front Right  
Paint / Corrosion -



15. Fender / Front Right  
Paint / Stone Chip -




16. Door Step / Front Left  
Interior / Holed -



17. Seat / Front Left  
Interior / Ripped -



18. Tailgate Upholstery / Back  
Interior / Scratched -



19. Door Step / Back Right  
Interior / Dented -



20. Seat / Front Right  
Interior / Holed -



## Mechanical Condition

### Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	NA
--------------	---	---------------	----

### Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

## Test Drive Inspection

Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering   Noise / Anomaly	✓		
General			
Test Driven Status	✓		
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

## Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)