



Mercedes A: 1WRD472

Vinnnumber:	WDD1770031N104094	Versionname:	
First Registrationdate:	20/08/2019	Fiscalpower:	
Expertise Mileage:	98381	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3628
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	1	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

	205/60/16/92 V			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				205/60 R 16 92 V
Tyre size FR				205/60 R 16 92 V
Tyre size RL				205/60 R 16 92 V
Tyre size RR				205/60 R 16 92 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	317,50
Ignition key, Missing, Replace	0,00



Interior, Damaged, Acceptable

0,00



Bumper F, Scratch(es), Repair and paint (complete)

289,07



Alloy rim RL polished, Chemical polution, Acceptable

0,00



Alloy rim FL polished, Chemical polution, Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Boot carpet, Dirty, Cleaning

28,43



Bumper R, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Chemical polution, Acceptable

0,00



Alloy rim RR polished, Chemical polution, Acceptable

0,00

