



MERCEDES-BENZ C-Klasse

C 250 CDI DPF Automatik

VIN NO WDD2040031A417907
Registration Number 031A417907



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-07-01	3	2	393722 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2010-06-18	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251008052229
Inspection Date / Place	2025-10-08 / HARTMANN Compound-Professionals GmbH Dorfmark	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	2143
Engine Size	2.1	No of Doors	4
Body Type	Sedan	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	149
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Alloys wheels	Bluetooth telephone interface	Front parking sensors
Remote central locking	Stability control	Central locking	Leather steering wheel
Rear parking sensors	Airbag Status	Anti-lock braking	Diesel particulate filter
Remote adjusting wing mirrors	Satellite navigation	Sunroof	Electrically folding wing mirrors
Radio			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front
Sunroof Type	Tilt/Slide Glass		

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	7	Extra Wheel - 2 Tyre Depth	7
Extra Wheel - 3 Tyre Depth	6	Extra Wheel - 4 Tyre Depth	6
Right Front Tyre Depth	5	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

19 Damages



4 Damages



Component		Damage	Comments
1	Rim / Front Left	Out of Bodywork / Scratch	
2	Rim / Back Right	Out of Bodywork / Scratch	
3	Rim / Front Right	Out of Bodywork / Scratch	
4	Rim / Back Left	Out of Bodywork / Scratch	
5	Wing Repeater / Left	Paint / Stone Chip	
6	Hood	Paint / Stone Chip	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Bumper / Back	Paint / Scratch / Scuff	
9	Window Cover / Front Right	Paint / Scratch / Scuff	
10	Seat / Front Right	Interior / Dirty	
11	TV DVD Screen / Front	Interior / Dysfunctional	
12	Seat / Front Left	Interior / Ripped	

13	Door / Front Left	Paint / Scratch / Scuff
14	Seat / Front Right	Interior / Ripped
15	Tailgate	Paint / Scratch / Scuff
16	Door / Front Right	Paint / Scratch / Scuff
17	Door / Back Left	Paint / Scratch / Scuff
18	Side Panel / Back Right	Paint / Scratch / Scuff
19	Door / Back Right	Paint / Scratch / Scuff
20	Door / Front Left	Paint / Scratch / Scuff
21	Hood	Bodywork / Dent / Dent
22	Hood	Bodywork / Dent / Dent
23	Door / Back Right	Paint / Scratch / Scuff



1. Rim / Front Left
Out of Bodywork / Scratch -




2. Rim / Back Right
Out of Bodywork / Scratch -




3. Rim / Front Right
Out of Bodywork / Scratch -



4. Rim / Back Left
Out of Bodywork / Scratch -



5. Wing Repeater / Left
Paint / Stone Chip -




6. Hood
Paint / Stone Chip -



7. Bumper / Back
Paint / Scratch / Scuff -




8. Bumper / Back
Paint / Scratch / Scuff -



9. Window Cover / Front Right
Paint / Scratch / Scuff -




10. Seat / Front Right
Interior / Dirty -



11. TV DVD Screen / Front
Interior / Dysfunctional -



12. Seat / Front Left
Interior / Ripped -



13. Door / Front Left
Paint / Scratch / Scuff -




14. Seat / Front Right
Interior / Ripped -




15. Tailgate
Paint / Scratch / Scuff -



16. Door / Front Right
Paint / Scratch / Scuff -



17. Door / Back Left
Paint / Scratch / Scuff -




18. Side Panel / Back Right
Paint / Scratch / Scuff -



19. Door / Back Right
Paint / Scratch / Scuff -



20. Door / Front Left
Paint / Scratch / Scuff -



21. Hood
Bodywork / Dent / Dent -



22. Hood
Bodywork / Dent / Dent -



23. Door / Back Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	!		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Hybrid/EV

Hybrid System Fault	NA
---------------------	----

Test Drive Inspection

Engine			
Engine Noise	!	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Steering Wheel			
Steering Noise / Anomaly	✓		
Brake			
Brake System Anomaly	✓		
Clutch			
Clutch Functioning	NA		
General			

Test Driven Status ✓

- ✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
- ! *Damages or malfunction detected that requires repairs by the buyer*
- NA *Not applicable*
- ☐ *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)