



MERCEDES-BENZ C-Klasse
C 180 BlueEFFICIENCY

VIN NO WDD2040491A652991
Registration Number 491A652991



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	2	2	163389 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2011-11-14	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20251006101338
Inspection Date / Place	2025-10-06 / SULOJA Mönchengladbach	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1796
Engine Size	1.8	No of Doors	4
Body Type	Sedan	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	157
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trafficsignrecognition	Airbag Status	Anti-lock braking	Bluetooth telephone interface
Front fog lamps	Remote central locking	Stability control	Central locking
Radio	USB Socket	Alloys wheels	Auxiliary Socket
Fatiguewarningsystem	Remote adjusting wing mirrors	Satellite navigation	CD Player
Leather steering wheel	Rain sensitive windscreen wipers		

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

9 Schäden



0 Schäden



Component	Damage	Comments
1 Corner Bumper / Front Left	Bodywork / Dent / Dent	
2 Corner Bumper / Front Right	Paint / Scratch / Scuff	
3 Windshield / Front	Glass Break	
4 Corner Bumper / Back Left	Bodywork / Breakage / Hole	
5 Corner Bumper / Back Right	Bodywork / Breakage / Hole	
6 Side Panel / Back Right	Paint / Scratch / Scuff	
7 Door / Back Right	Paint / Scratch / Scuff	
8 Door / Front Right	Paint / Scratch / Scuff	
9 Mirror Shell / Front Right	Paint / Scratch / Scuff	



1. Corner Bumper / Front Left
Bodywork / Dent / Dent -



2. Corner Bumper / Front Right
Paint / Scratch / Scuff -



3. Windshield / Front
Glass Break -



4. Corner Bumper / Back Left
Bodywork / Breakage / Hole -



5. Corner Bumper / Back Right
Bodywork / Breakage / Hole -




6. Side Panel / Back Right
Paint / Scratch / Scuff -



7. Door / Back Right
Paint / Scratch / Scuff -



8. Door / Front Right
Paint / Scratch / Scuff -



9. Mirror Shell / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓
Other Equipments	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

The Gears Scratch / Skip / Abnormal Operation Engine Noise

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status Not Performed

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)