



MERCEDES-BENZ C-Klasse

C 180 T (BlueEFFICIENCY) 7G-TRONIC

VIN NO WDD2042311G189473
Registration Number 311G189473



MOT Date

2026-09-01

Last Service



Number of Owners

2

Last Service Mileage



Number of Keys

2

First Registration Date

2013-08-05

Odometer Reading

100249 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250924160537
Inspection Date / Place	2025-09-24 / BCA Neuss	Cosmetic Grade	4



Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1595
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	139
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

USB Socket	Alloys wheels	Bluetooth telephone interface	Front parking sensors
Remote central locking	Roof rails	Stability control	Leather steering wheel
Rear parking sensors	Airbag Status	Anti-lock braking	Cruise control
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Electrically folding wing mirrors
Radio			

Equipment Details


Air Conditioning	Three Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

15 Schäden




5 Schäden



1

Component		Damage	Comments
1	Side Panel / Back Right	Paint / Poor Previous Repair	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Rim / Front Left	Out of Bodywork / Scratch	
5	Panel Filling / Front Left	Interior / Broken	
6	Seat / Front Left	Interior / Ripped	
7	B Pillar / Center Left	Paint / Scratch / Scuff	
8	Door / Back Left	Paint / Scratch / Scuff	
9	Panel Filling / Back Left	Interior / Scratched	
10	Pillar / Back Left	Paint / Scratch / Scuff	
11	Side Panel / Back Left	Paint / Scratch / Scuff	
12	Bumper / Back	Paint / Scratch / Scuff	

13	Side Panel / Back Right	Paint / Scratch / Scuff
14	Rim / Back Right	Out of Bodywork / Scratch
15	Door / Back Right	Bodywork / Dent / Dent
16	Pillar / Back Right	Paint / Scratch / Scuff
17	Door / Front Right	Paint / Scratch / Scuff
18	Panel Filling / Front Right	Interior / Scratched
19	Rim / Front Right	Out of Bodywork / Scratch
20	Other	Interior / Broken



1. Side Panel / Back Right
Paint / Poor Previous Repair -




2. Bumper / Front
Paint / Scratch / Scuff -



3. Bumper / Front
Paint / Scratch / Scuff -



4. Rim / Front Left
Out of Bodywork / Scratch -




5. Panel Filling / Front Left
Interior / Broken -



6. Seat / Front Left
Interior / Ripped -



7. B Pillar / Center Left
Paint / Scratch / Scuff -




8. Door / Back Left
Paint / Scratch / Scuff -




9. Panel Filling / Back Left
Interior / Scratched -



10. Pillar / Back Left
Paint / Scratch / Scuff -



11. Side Panel / Back Left
Paint / Scratch / Scuff -



12. Bumper / Back
Paint / Scratch / Scuff -



13. Side Panel / Back Right
Paint / Scratch / Scuff -




14. Rim / Back Right
Out of Bodywork / Scratch -



15. Door / Back Right
Bodywork / Dent / Dent -



16. Pillar / Back Right
Paint / Scratch / Scuff -



17. Door / Front Right
Paint / Scratch / Scuff -



18. Panel Filling / Front Right
Interior / Scratched -



19. Rim / Front Right
Out of Bodywork / Scratch -



20.
Interior / Broken -

Mechanical Condition

Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	!
Parking Sensors / Cameras Functioning	✓	Other Equipments	✓

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	!

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)