



MERCEDES C BERLINE: 1WRL592			
Vinnumber:	WDD2050011R517172	Versionname:	C 200 d
First Registrationdate:	22/08/2019	Fiscalpower:	
Expertise Mileage:	95865	Power Kw:	118
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1422
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	A5 - 219 dagen		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	SD present		
Limited Technical Inspection			
Tyres			
Summer tyres:	205/60/16/92 V		
	Fr.L.	Continental: 6 mm	Fr.R.
	Re.L.	Continental: 6 mm	Re.R.
			Continental: 6 mm
Tyre profile depth FL			6.0
Tyre profile depth FR			6.0
Tyre profile depth RL			6.0
Tyre profile depth RR			6.0
Tyre size FL			205/60 R 16 92 V
Tyre size FR			205/60 R 16 92 V
Tyre size RL			205/60 R 16 92 V
Tyre size RR			205/60 R 16 92 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			1100,81
Bonnet, Stone chip(s), Acceptable			0,00



Bumper F, Scratch(es), Acceptable

0,00



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)

536,65



Alloy rim FL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Repair and paint (complete)

129,66



Wing RR, Dent(s) and scratch(es), Acceptable

0,00



Door RR, Scratch(es), Repair and paint (complete)	434,50
---	--------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Roof pillar R, Dent(s), Acceptable	0,00
------------------------------------	------

