



MERCEDES-BENZ C-Klasse

C 200 T 9G-TRONIC

VIN NO WDD2052771F920727
Registration Number 771F920727



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	1	2	84956 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2019-07-03	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250916160923
Inspection Date / Place	2025-09-16 / BCA Berlin	Cosmetic Grade	3


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Black	Engine Size (cc)	1497
Engine Size	1.5	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	142
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Alloys wheels	Cabin Pre Heating	Front parking sensors
Remote central locking	Roof rails	Stability control	Radio
Airbag Status	Anti-lock braking	Cruise control	Remote adjusting wing mirrors
Reversing Camera	Satellite navigation	LED Headlamps	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

5 Schäden



0 Schäden




Component		Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	
2	Hood	Paint / Chipping	
3	Windshield / Front	Paint / Chipping	
4	Side Panel / Back Left	Paint / Scratch / Scuff	
5	Door / Front Left	Paint / Scratch / Scuff	



1. Bumper / Front
Paint / Scratch / Scuff -



2. Hood
Paint / Chipping -



3. Windshield / Front
Paint / Chipping -



4. Side Panel / Back Left
Paint / Scratch / Scuff -



5. Door / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓
Other Equipments	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)