



MERCEDES-BENZ E-Klasse
E 350 CDI DPF Coupe BlueEFFICIENCY 7G-TRONIC

VIN NO WDD2073221F017978
Registration Number 221F017978



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-11-01	2	2	234236 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2009-09-24	Germany

Inspection Report Summary


Customer	BCA Online	Report Number	P20250924150219
Inspection Date / Place	2025-09-24 / BCA Heidenheim	Cosmetic Grade	9

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	2987
Engine Size	3.0	No of Doors	2
Body Type	Coupe	Drive Train	Rear
Seat Colour		No of Seats	4
Seat Covering Name	Hellbraun	Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	179
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Diesel particulate filter	Front parking sensors
Remote central locking	Stability control	CD - multichanger	Radio
Alloys wheels	Cruise control	Front fog lamps	Remote adjusting wing mirrors
Satellite navigation	Sunroof	Leather steering wheel	Rear parking sensors

Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front	Sunroof Type	Opening Panoramic



Wheels & Tyres

Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

29 Schäden

4 Schäden




Component		Damage	Comments
1	TV DVD Screen / Front	Interior / Dysfunctional	
2	Fender / Front Left	Paint / Poor Previous Repair	
3	Fender / Front Right	Paint / Poor Previous Repair	
4	Door / Front Right	Paint / Poor Previous Repair	
5	Side Panel / Back Right	Paint / Poor Previous Repair	
6	Tailgate	Paint / Poor Previous Repair	
7	Side Panel / Back Left	Paint / Poor Previous Repair	
8	Door / Front Left	Paint / Poor Previous Repair	
9	Windshield / Front	Glass Break / Impact	
10	Bumper / Front	Paint / Scratch / Scuff	
11	Bumper / Front	Paint / Scratch / Scuff	
12	Bumper / Front	Bodywork / Breakage	


13	Hood	Bodywork / Dent / Dent
14	Hood	Bodywork / Dent / Dent
15	Hood	Bodywork / Dent / Dent
16	Rim / Back Right	Out of Bodywork / Scratch
17	Roof Molding / Right	Missing Part
18	Door / Front Right	Bodywork / Dent / Dent
19	Door / Front Right	Bodywork / Dent / Dent
20	Door / Front Right	Paint / Scratch / Scuff
21	Side Panel / Back Right	Bodywork / Dent / Dent
22	Side Panel / Back Right	Paint / Scratch / Scuff
23	Side Panel / Back Right	Bodywork / Dent / Dent
24	Bumper / Back	Paint / Scratch / Scuff
25	Bumper / Back	Paint / Scratch / Scuff
26	Tailgate	Paint / Scratch / Scuff
27	Tailgate	Paint / Scratch / Scuff
28	Rim / Back Left	Out of Bodywork / Scratch
29	Side Panel / Back Left	Bodywork / Dent / Dent
30	Door / Front Left	Paint / Scratch / Scuff
31	Seat / Front Left	Interior / Scratched
32	Panel Filling / Front Right	Interior / Broken
33	Panel Filling / Front Left	Interior / Broken




1. TV DVD Screen / Front Interior / Dysfunctional -




2. Fender / Front Left Paint / Poor Previous Repair -




3. Fender / Front Right Paint / Poor Previous Repair -




4. Door / Front Right Paint / Poor Previous Repair -




5. Side Panel / Back Right Paint / Poor Previous Repair -



6. Tailgate Paint / Poor Previous Repair -



7. Side Panel / Back Left
Paint / Poor Previous Repair -



8. Door / Front Left
Paint / Poor Previous Repair -



9. Windshield / Front
Glass Break / Impact -



10. Bumper / Front
Paint / Scratch / Scuff -



11. Bumper / Front
Paint / Scratch / Scuff -



12. Bumper / Front
Bodywork / Breakage -



13. Hood
Bodywork / Dent / Dent -



14. Hood
Bodywork / Dent / Dent -




15. Hood
Bodywork / Dent / Dent -




16. Rim / Back Right
Out of Bodywork / Scratch -




17. Roof Molding / Right
Missing Part -




18. Door / Front Right
Bodywork / Dent / Dent -




19. Door / Front Right
Bodywork / Dent / Dent -



20. Door / Front Right
Paint / Scratch / Scuff -



21. Side Panel / Back Right
Bodywork / Dent / Dent -



22. Side Panel / Back Right
Paint / Scratch / Scuff -



23. Side Panel / Back Right
Bodywork / Dent / Dent -



24. Bumper / Back
Paint / Scratch / Scuff -



25. Bumper / Back
Paint / Scratch / Scuff -



26. Tailgate
Paint / Scratch / Scuff -



27. Tailgate
Paint / Scratch / Scuff -



28. Rim / Back Left
Out of Bodywork / Scratch -




29. Side Panel / Back Left
Bodywork / Dent / Dent -



30. Door / Front Left
Paint / Scratch / Scuff -



31. Seat / Front Left
Interior / Scratched -



32. Panel Filling / Front Right
Interior / Broken -



33. Panel Filling / Front Left
Interior / Broken -

Mechanical Condition

Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓
Parking Sensors / Cameras Functioning	✓	Other Equipments	✓

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	NA
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)