



MERCEDES-BENZ E-Klasse

E 200 CGI BlueEFFICIENCY

VIN NO WDD2120481A093928
Registration Number 481A093928



MOT Date

2025-03-01

Last Service



Number of Owners

3

Last Service Mileage



Number of Keys

2

First Registration Date

2010-03-03

Odometer Reading

151051 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250807144200
Inspection Date / Place	2025-08-07 / BCA Neuss	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	No
Colour	Black	Engine Size (cc)	1796
Engine Size	1.8	No of Doors	4
Body Type	Sedan	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz/grau	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	165
Gearbox Type	Manual		

Vehicle History & Documents


Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			











Equipment

Airbag Status	Anti-lock braking	Cruise control	Remote adjusting wing mirrors
Satellite navigation	Xenon headlamps	CD Player	Radio
Alloys wheels	Bluetooth telephone interface	Front parking sensors	Remote central locking
Stability control	CD - multichanger	Leather steering wheel	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4
Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

18 Schäden



1 Schäden



Component		Damage	Comments
1	Hood	Paint / Stone Chip	
2	Bumper / Front	Bodywork / Breakage / Crack	
3	Wing Expander / Front Left	Paint / Scratch / Scuff	
4	Door / Front Left	Bodywork / Dent / Dent	
5	Panel Filling / Front Left	Interior / Scraped	
6	Door / Front Left	Paint / Scratch / Scuff	
7	Door / Back Left	Paint / Scratch / Scuff	
8	Pillar / Back Left	Paint / Scratch / Scuff	
9	Door / Back Left	Paint / Scratch / Scuff	
10	Rim / Front Left	Out of Bodywork / Scratch	
11	Bumper / Back	Bodywork / Breakage / Crack	
12	Roof	Paint / Scratch / Scuff	

13	Rim / Back Right	Out of Bodywork / Scratch
14	Door / Back Right	Paint / Scratch / Scuff
15	Pillar / Back Right	Paint / Scratch / Scuff
16	Door / Front Right	Paint / Scratch / Scuff
17	Door Handle / Front Right	Paint / Scratch / Scuff




1. Hood
Paint / Stone Chip -



2. Bumper / Front
Bodywork / Breakage / Crack -




3. Wing Expander / Front Left
Paint / Scratch / Scuff -



4. Door / Front Left
Bodywork / Dent / Dent -



5. Panel Filling / Front Left
Interior / Scraped -



6. Door / Front Left
Paint / Scratch / Scuff -



7. Door / Back Left
Paint / Scratch / Scuff -




8. Pillar / Back Left
Paint / Scratch / Scuff -



9. Door / Back Left
Paint / Scratch / Scuff -



10. Rim / Front Left
Out of Bodywork / Scratch -




11. Bumper / Back
Bodywork / Breakage / Crack -



12. Roof
Paint / Scratch / Scuff -




13. Rim / Back Right
Out of Bodywork / Scratch -




14. Door / Back Right
Paint / Scratch / Scuff -



15. Pillar / Back Right
Paint / Scratch / Scuff -



16. Door / Front Right
Paint / Scratch / Scuff -



17. Door Handle / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

No Dashboard Lights	❗	Display Defect	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Leak Visible	✓	Engine Starts	❗
---------------------	---	---------------	---

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Clutch

Clutch Functioning	✓
--------------------	---

General

Test Driven Status	✓
--------------------	---

✓ **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

❗ **Damages or malfunction detected that requires repairs by the buyer**

NA **Not applicable**

☐ **Not tested**

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)