



MERCEDES-BENZ B-Klasse B 180 (BlueEFFICIENCY)

VIN NO WDD2462421J072506
Registration Number 421J072506



MOT Date

2026-10-01

Last Service



Number of Owners

2

Last Service Mileage



Number of Keys

2

First Registration Date

2012-06-11

Odometer Reading

273613 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250714073941
Inspection Date / Place	2025-07-14 / ARS Altmann AG Riedstadt	Cosmetic Grade	4


Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Brown	Engine Size (cc)	1595
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	137
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Airbag Status	Anti-lock braking	Front parking sensors
Remote adjusting wing mirrors	Satellite navigation	CD Player	Leather steering wheel
Rear parking sensors	USB Socket	Alloys wheels	Bluetooth telephone interface
Heated wing mirrors	Remote central locking	Stability control	Electrically folding wing mirrors
Radio			


Equipment Details

Air Conditioning	Yes	Alloy Wheel Size	16
Satellite Navigation	Beckermaps Modul fehlt	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage




Component		Damage	Comments
1	Hood	Paint / Stone Chip	
2	Windshield / Front	Paint / Chipping	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Bumper / Front	Bodywork / Dent / Dent	
5	Door / Front Left	Bodywork / Dent / Dent	
6	Door / Back Left	Bodywork / Dent / Dent	
7	Door / Front Left	Paint / Scratch / Scuff	
8	Panel Filling / Front Left	Interior / Dented	
9	Seat / Front Left	Interior / Scratched	
10	Fender / Back Left	Paint / Scratch / Scuff	
11	Door / Back Left	Paint / Scratch / Scuff	
12	Pillar / Back Left	Bodywork / Dent / Dent	
13	Rear Window / Back	Glass Break / Scratch / Scratch	

14	Bumper / Back	Paint / Scratch / Scuff
15	Bumper / Back	Bodywork / Dent / Dent
16	Fender / Back Right	Bodywork / Dent / Dent
17	Door / Back Right	Bodywork / Dent / Dent
18	Pillar / Back Right	Bodywork / Dent / Dent
19	Rocker Panel / Center Right	Paint / Scratch / Scuff
20	Door / Front Right	Paint / Scratch / Scuff
21	Door / Back Right	Bodywork / Dent / Dent




1. Hood
Paint / Stone Chip -



2. Windshield / Front
Paint / Chipping -




3. Bumper / Front
Paint / Scratch / Scuff -



4. Bumper / Front
Bodywork / Dent / Dent -



5. Door / Front Left
Bodywork / Dent / Dent -



6. Door / Back Left
Bodywork / Dent / Dent -



7. Door / Front Left
Paint / Scratch / Scuff -




8. Panel Filling / Front Left
Interior / Dented -



9. Seat / Front Left
Interior / Scratched -



10. Fender / Back Left
Paint / Scratch / Scuff -



11. Door / Back Left
Paint / Scratch / Scuff -




12. Pillar / Back Left
Bodywork / Dent / Dent -



13. Rear Window / Back
Glass Break / Scratch / Scratch -




14. Bumper / Back
Paint / Scratch / Scuff -



15. Bumper / Back
Bodywork / Dent / Dent -



16. Fender / Back Right
Bodywork / Dent / Dent -



17. Door / Back Right
Bodywork / Dent / Dent -




18. Pillar / Back Right
Bodywork / Dent / Dent -



19. Rocker Panel / Center Right
Paint / Scratch / Scuff -



20. Door / Front Right
Paint / Scratch / Scuff -



21. Door / Back Right
Bodywork / Dent / Dent -

Mechanical Condition

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Equipments Test

Navigation System	!	Central Locking	✓
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Other Equipments	✓
Main & Spare Keys Functioning	✓	Parking Sensors / Cameras Functioning	✓

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)