

WDF44760313680325

MERCEDES-BENZ Vito Vito 114 CDI Lang VA


TECHNICAL CONDITION ⚙️

Engine	Brakes	Steering
Engine starts ✓	Brake operation ✓	Sounds normal ✓
Engine operation ✓		
Engine compartment dry (oil) ✓	Clutch	Gear Box
Fume quantity ✓	Clutch operation ✓	Automatic shift ⊖
Sounds normal ✓	Idle sounds normal ✓	Manual shif ⊖
	Clutch biting point ✓	Warning light OK ✓

COMPLAINT NOTE ⓘ

The technical check includes a visual check of the vehicles without removal of any components.
The condition of the mechanical components cannot be rated.

LEVELS 💧

Coolant fluid	✓
Brakes fluid	✓

EQUIPMENT TEST +

Electric windows test	✓
Audio equipment	✓
Navigation equipment	⊖
AC / Heating system	✓
Central lock system test	✓

TYRES 🛞

Profile depths

FL 4 mm **FR** 4 mm

BR 5 mm **BL** 5 mm

Additional tyre profile depths

A ⊖ **B** ⊖

C ⊖ **D** ⊖

CONTROL LIGHTS 🚦

Dashboard	✓
ABS	✓
Oil	⊖
Airbag	✓
Engine	✓
Brakes	✓
Steering	✓
DPF	⊖
Diesel heaters	✓
Traction control / ESP / Stability control	⊖
4x4	⊖
Alternator / Battery	✓



No defects recognizable, good condition or positive tests based on vehicle's age and mileage.



Registered damage that needs to be repaired by the buyer.



Not verifiable.