



MERCEDES VITO (30)
VITO 109 CDI 2.7t COMPACT

VIN NO WDF63960113092378

Registration Number FM603XF



MOT Date



Last Service



Number of Owners




Last Service Mileage




Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250911084234
Inspection Date / Place	2025-09-11 / BCA ANGOULEME	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Qualified - Normal Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	2148
Engine Size	2.1	No of Doors	5
Body Type	Box Wagon	Drive Train	Rear
Seat Colour		No of Seats	3
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Cruise control	Radio	Power assisted steering
-----------------	----------------	-------	-------------------------

Equipment Details


Seat Heating	No	Air Conditioning	No
--------------	----	------------------	----

Cosmetic Damage

31 Dommages



6 Dommages



Component		Damage	Comments
1	Panel Filling / Front Left	Interior / Dirty	
2	Seat / Front Left	Interior / Holed	
3	Seat / Front Left	Interior / Dirty	
4	Panel Filling / Front Right	Interior / Scraped	
5	Panel Filling / Front Right	Interior / Dirty	
6	Seat / Front Right	Interior / Dirty	
7	Hood	Paint / Chipping	
8	Mirror / Front Left	Paint / Chipping	
9	Mirror / Front Left	Paint / Scratch / Scuff	
10	Door / Front Left	Bodywork / Poor Previous Repair	
11	Door / Front Left	Paint / Scratch / Scuff	
12	Door / Front Left	Paint / Chipping	

13	Fender / Back Left	Paint / Corrosion
14	Fender / Back Left	Paint / Chipping
15	Fender / Back Left	Bodywork / Poor Previous Repair
16	Fender / Back Left	Paint / Scratch / Scuff
17	Fender / Back Left	Paint / Scratch / Scuff
18	Fender / Back Left	Paint / Scratch / Line
19	Tailgate	Paint / Poor Previous Repair
20	Tailgate	Paint / Poor Previous Repair
21	Tailgate	Paint / Chipping
22	Fender / Back Right	Paint / Poor Previous Repair
23	Fender / Back Right	Bodywork / Dent / Dent
24	Fender / Back Right	Paint / Poor Previous Repair
25	Fender / Back Right	Paint / Chipping
26	Door / Back Right	Paint / Chipping
27	Door / Back Right	Paint / Poor Previous Repair
28	Door / Back Right	Paint / Chipping
29	Door / Back Right	Paint / Scratch / Line
30	Door / Back Right	Paint / Chipping
31	Door / Front Right	Paint / Scratch / Scuff
32	Door / Front Right	Paint / Chipping
33	Door / Front Right	Paint / Chipping
34	Door / Front Right	Paint / Scratch / Line
35	Fender / Front Right	Paint / Chipping
36	Fender / Front Right	Bodywork / Breakage
37	Fender / Front Right	Paint / Scratch / Line



1. Panel Filling / Front Left
Interior / Dirty -



2. Seat / Front Left
Interior / Holed -



3. Seat / Front Left
Interior / Dirty -



4. Panel Filling / Front Right
Interior / Scraped -



5. Panel Filling / Front Right
Interior / Dirty -



6. Seat / Front Right
Interior / Dirty -



7. Hood
Paint / Chipping -



8. Mirror / Front Left
Paint / Chipping -



9. Mirror / Front Left
Paint / Scratch / Scuff -



10. Door / Front Left
Bodywork / Poor Previous Repair -



11. Door / Front Left
Paint / Scratch / Scuff -



12. Door / Front Left
Paint / Chipping -



13. Fender / Back Left
Paint / Corrosion -



14. Fender / Back Left
Paint / Chipping -



15. Fender / Back Left
Bodywork / Poor Previous Repair -



16. Fender / Back Left
Paint / Scratch / Scuff -



17. Fender / Back Left
Paint / Scratch / Scuff -



18. Fender / Back Left
Paint / Scratch / Line -



19. Tailgate
Paint / Poor Previous Repair -



20. Tailgate
Paint / Poor Previous Repair -



21. Tailgate
Paint / Chipping -



22. Fender / Back Right
Paint / Poor Previous Repair -



23. Fender / Back Right
Bodywork / Dent / Dent -



24. Fender / Back Right
Paint / Poor Previous Repair -



25. Fender / Back Right
Paint / Chipping -



26. Door / Back Right
Paint / Chipping -



27. Door / Back Right
Paint / Poor Previous Repair -



28. Door / Back Right
Paint / Chipping -



29. Door / Back Right
Paint / Scratch / Line -



30. Door / Back Right
Paint / Chipping -



31. Door / Front Right
Paint / Scratch / Scuff -



32. Door / Front Right
Paint / Chipping -



33. Door / Front Right
Paint / Chipping -



34. Door / Front Right
Paint / Scratch / Line -



35. Fender / Front Right
Paint / Chipping -



36. Fender / Front Right
Bodywork / Breakage -



37. Fender / Front Right
Paint / Scratch / Line -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.