

ZB091N

ZB091N · KOMBI 2.0 TDCi 105PK 320 L2H2 Trend · 26 September 2025 ·
Schiphol

Specifications

License Plate Number	ZB091N	VIN	WF01XXTTG1KK71863
Manufacturer	FORD	Cylinder Capacity	1.995 ^{cm³}
Model	Transit Custom	Transmission Type	Handmatig geschakelde transmissie6
Model Versions	KOMBI 2.0 TDCi 105PK 320 L2H2 Trend	MOT	05-06-2026
Body Type	VAN	First Admission	30-04-2019
Color	White	First Registration	30-04-2019
Paint Type	Matte	Odometer	148.370 ^{Km}
BPM	€ 25.971	Numer Of Keys	1
Production Year	2019	Interior	Grey
KW	77	Number Headrests	9
Fuel Type	Diesel		

Images



Accessories

ABS

Airbags

Audio System

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Manual air conditioning

Steering wheel multifunction

Windscreen – Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Rear Left	7 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Front Right	4 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Rear Right	7 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Fully Fledged					
Spare Tire Profile	8 ^{mm}					



Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Sleutel	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Drivers seat	Missing	Verstelknop	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Broken	Gordelhouder	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Broken	Gordelhouder	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Roof	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Afdekkapje en stootstrip	Replace & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	3 x	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Mirror - leftside	Damaged	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Hood	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Small dent(s)	Kentekenplaat	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	Dislocated / Loose	Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Rear	Missing	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Front	Missing	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Front Right	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Mirror - Rightside	Small scratch(es)	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Dent(s)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Dent(s)	Rearbar	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Other	Stickers	Remove	No