

X679KS

X679KS · 2.0 TDCI 130pk 310 L2H1 Automaat S&S Titanium + luchtvering · 24
September 2025 · Schiphol

Specifications

License Plate Number	X679KS	Cylinder Capacity	1.995 ^{cm3}
Manufacturer	FORD	Transmission Type	Handmatig geschakelde transmissie6
Model	Tourneo Custom	MOT	16-06-2026
Model Versions	2.0 TDCI 130pk 310 L2H1 Automaat S&S Titanium + luchtvering	First Admission	16-06-2023
Body Type	5 door hatchback	First Registration	06-12-2023
Color	Silver	License Plate 1a Available	
Paint Type	Metallic	VAT/Marge	BTW
BPM	€ 36.989	Odometer	64.368 ^{Km}
Production Year	2023	Numer Of Keys	2
KW	95	Interior	Darkgrey - Cloth
Fuel Type	Diesel	Number Headrests	8
VIN	WF01XXTTG1PL53110		

Images





Accessories

ABS

Airbags

ASR

Audio System

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric windows front

Electrically adjustable exterior mirrors

ESP

Fog lights

Front & rear parking sensors

Leather steering wheel

Manual air conditioning

Rear view camera

Seat heating

Side bars

Steering wheel multifunction

Windscreen – Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Rear Left	8 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Front Right	4 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Rear Right	8 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Fully Fledged					
Spare Tire Profile	5 ^{mm}					

Damages



Damage Part

Frontdoor – Right

Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Reardoor – Right

Damage Type

Dent(s) & Scratch(es)

Repair Type

Panelbeating &
Spray

Acceptable

No



Damage Part

Fender – Rear Right

Damage Type

Dent(s) & Scratch(es)

Repair Type

Panelbeating &
Spray

Acceptable

No



Damage Part

spoiler FB

Damage Type

Scratch(es)

Repair Type

Panelbeating &
Spotrepair

Acceptable

No



Damage Part

Frontdoor – Left

Damage Type

Small dent(s)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Fender – Rear Left

Damage Type

Broken

Notes

Stootlijst krassen

Repair Type

Replace

Acceptable

No



Damage Part

Damage Type

Repair Type


Acceptable

Fender – Rear Left

Dent(s) & Scratch(es)

Panelbeating &
Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Roof

Dent(s) & Scratch(es)

Panelbeating &
Spray

No