

X200LN

X200LN · 2.0 TDCI 130pk 310 L2H1 Automaat S&S Titanium + luchtvering · 17
September 2025 · Schiphol

Specifications

License Plate Number	X200LN	Cylinder Capacity	1.995 ^{cm3}
Manufacturer	FORD	Transmission Type	Handmatig geschakelde transmissie6
Model	Tourneo Custom	MOT	16-06-2026
Model Versions	2.0 TDCI 130pk 310 L2H1 Automaat S&S Titanium + luchtvering	First Admission	16-06-2023
Body Type	5 door hatchback	First Registration	14-12-2023
Color	Silver	License Plate 1a Available	
Paint Type	Metallic	VAT/Marge	BTW
BPM	€ 35.177	Odometer	77.065 ^{Km}
Production Year	2023	Numer Of Keys	2
KW	95	Interior	Darkgrey - Cloth
Fuel Type	Diesel	Number Headrests	8
VIN	WF01XXTTG1PL53116		

Images





Accessories

ABS

Airbags

ASR

Audio System

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric windows front

Electrically adjustable exterior mirrors

ESP

Fog lights

Front & rear parking sensors

Leather steering wheel

Manual air conditioning

Rear view camera

Seat heating

Steering wheel multifunction

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	7 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Rear Left	9 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Front Right	7 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Rear Right	9 ^{mm}	Vredestein	215 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Fully Fledged					
Spare Tire Profile	9 ^{mm}					

Damages



Damage Part

Fender – Rear Left

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Frontdoor – Left



Damage Type

small dents / small scratches

Repair Type

Restyle / Polish

Acceptable

No



Damage Part

Wheelcover - Left Rear

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part	Damage Type	Repair Type	Acceptable
Cargodoor - Right	Small dent(s)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Stootlijst krassen	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Small dent(s)	Panelbeating & Spotrepair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Dent(s)	Sidebar rechts vervormd	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Dislocated / Loose	Kentekenplaat voorzijde vervormd	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Dent(s)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Front	Missing	Replace	No