


Vehicle details

VIN	WF02XXERK 2LL81136	Brand	FORD	Maintenance date	-
Licence Plate	K9-86-KL	Model	PUMA 1.0 EcoBoost Hybrid Titanium 5d	Maintenance mileage	-
Registration date	06/01/2021	Year	2021	Exterior Color	Blue Solid
Odometer	125 196 km	Engine size	999	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	11/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Remote key	✓
Sat Nav CD ROM Software	✓
Spare key	✗

Tyres

Goodyear 215/55/17 Summer 4.0 mm	Goodyear 215/55/17 Summer 2.5 mm
Goodyear 215/55/17 Summer 6.0 mm	Goodyear 215/55/17 Summer 5.0 mm



Exterior

1



●●

Part	Wing
Position	Front left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

6



●●●

Part	Tailgate / Boot door
Position	-
Damages	Dented
Severity	-
Repair mode	Replace

7



●●●●

Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8



●●

Part	Unpainted bumper
Position	Back
Damages	Broken
Severity	-
Repair mode	Replace

9



●●

Part	Bumper
Position	Back right
Damages	Misaligned
Severity	-
Repair mode	Adjust

10



●●

Part	Door
Position	Back right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair


11



●●●●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

13



●●

Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

Interior damage

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

4



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace

5



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace


14



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

Others

12



Part	Damage appraisal
Position	Front
Damages	Stone impact
Severity	-
Repair mode	For info