



Ford Transit (Segm. B3): 2BKA614

Vinnumber:	WF0AXXTTRAMC67512	Versionname:	Transit CC 350E L4 Trend 2.0TD 130pk/cv FWD
First Registrationdate:	15/12/2021	Fiscalpower:	
Expertise Mileage:	135748	Power Kw:	96
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Battery functioning	No		
Registration Certificate Car (BE)	Yes		
Maintenance	OK		

Options

Type of Maintenance book	Maintenancebook present	Type of Tow bar	No Tow bar
Type of GPS storage	N.A.		
GPS			
Number of keys total	2		

Tyres


Tyre size RL				235/65 R 16 113 R
Tyre type FL				All seasons
Tyre type RL				All seasons
Tyre profile depth FR				6.0
Tyre profile depth RR				7.0
Tyre size FR				235/65 R 16 113 R
Tyre make FR				255
235/65/16/113 R				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm
Tyre size RR				235/65 R 16 113 R
Tyre make RR				255
Tyre profile depth FL				6.0
Tyre size FL				235/65 R 16 113 R
Tyre make FL				255
Tyre profile depth RL				7.0
Tyre type FR				All Seasons
Tyre type RR				All Seasons
Tyre make RL				255

Assistance equipment

Number of charging cables (normal)	0	Jack	No
Spare wheel	No		
Number of charging cables (rapid charge)	0		

Interior, Dirty, Cleaning





Engine, Not functioning (well), Check



Bumper F, Crack, Replace



Mirror side repeater L, Waterinfiltration, Replace



Wing FL, Dent(s), Paintless dent repair



Wing trim FL, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Sill trim L, Scratch(es), Replace



Wheel cover RL, Missing, Replace



Spare wheel, Missing, Replace



Jack, Missing, Replace



Wheel cover RR, Missing, Replace



Outside rear-view mirror housing R, Scratch(es), Acceptable



Door FR, Dent(s), Paintless dent repair



Door trim FR, Scratch(es), Replace



Wing trim FR, Scratch(es), Replace



Wheel cover FR, Missing, Replace



Door trim FR, Scratch(es), Replace



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Bodywork, Not original part, Remove lettering



Bodywork, Damaged, Check

