



FORD Ka

VIN NO WF0BXXWPRBYR29958
Registration Number PRBYR29958



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250908102846
Inspection Date / Place	2025-09-08 / Dello Eppendorf/Hamburg	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	1299
Engine Size	1.3	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	4
Seat Covering Name	Grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	150
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Central locking	Airbag Status	Radio
---------------	-----------------	---------------	-------

Equipment Details

Air Conditioning	Yes
------------------	-----


Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
------------------------	---	-----------------------	---


Right Rear Tyre Depth	6	Left Rear Tyre Depth	6
-----------------------	---	----------------------	---

Cosmetic Damage

17 Schäden




0 Schäden



Component		Damage	Comments
1	Door / Front Left	Paint / Poor Previous Repair	
2	Roof	Paint / Poor Previous Repair	
3	Door / Front Left	Bodywork / Dent / Dent	
4	Door / Front Left	Bodywork / Dent / Dent	
5	Fender / Back Left	Bodywork / Dent / Dent	
6	Tailgate	Bodywork / Dent / Dent	
7	Door / Front Right	Bodywork / Dent / Dent	
8	Rocker Panel / Center Right	Paint / Corrosion	
9	Rocker Panel / Center Left	Paint / Corrosion	
10	Pillar / Front Left	Paint / Corrosion	
11	Roof	Paint / Corrosion	
12	Fender / Front Right	Paint / Chipping	


13	Rocker Panel / Center Right	Paint / Corrosion
14	Rocker Panel / Center Right	Paint / Corrosion
15	Rocker Panel / Center Left	Paint / Corrosion
16	Rocker Panel / Center Left	Paint / Corrosion
17	Door / Front Left	Paint / Chipping




1. Door / Front Left
Paint / Poor Previous Repair -



2. Roof
Paint / Poor Previous Repair -




3. Door / Front Left
Bodywork / Dent / Dent -




4. Door / Front Left
Bodywork / Dent / Dent -



5. Fender / Back Left
Bodywork / Dent / Dent -



6. Tailgate
Bodywork / Dent / Dent -




7. Door / Front Right
Bodywork / Dent / Dent -



8. Rocker Panel / Center Right
Paint / Corrosion -



9. Rocker Panel / Center Left
Paint / Corrosion -




10. Pillar / Front Left
Paint / Corrosion -



11. Roof
Paint / Corrosion -



12. Fender / Front Right
Paint / Chipping -



13. Rocker Panel / Center Right
Paint / Corrosion -



14. Rocker Panel / Center Right
Paint / Corrosion -



15. Rocker Panel / Center Left
Paint / Corrosion -



16. Rocker Panel / Center Left
Paint / Corrosion -



17. Door / Front Left
Paint / Chipping -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Alternator / Battery	✓		

Equipments Test

Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	AC / Heating System	✓
Other Equipments	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Engine

Engine Leak Visible	✓	Engine Starts	✓
---------------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering Noise / Anomaly	✓
----------------------------	---

Engine

Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓

Clutch

Clutch Functioning	✓
--------------------	---

Brake

Brake System Anomaly	✓
----------------------	---

General

Test Driven Status	✓
--------------------	---

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

 *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)