



FORD C-Max 2007 Diesel

c-max 1.6 tdcI Titanium Esp 90cv

VIN NO WF0EXXGCDE8T21167
Registration Number DX263DF



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-05-21	-	-	165903 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2009-05-25	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250925142846
Inspection Date / Place	2025-09-25 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Silver	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	5
Body Type	MPV	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	124

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Parcel Shef	Remote central locking
Stability control	Power assisted steering	Digital Radio	Remote adjusting wing mirrors
Trip Computer			


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	KLEBER KLEBER-DYNAXER HP4	205/50//R17 - 93W / 2 mm
	KLEBER KLEBER-DYNAXER HP4	205/50//R17 - 93W / 2 mm
	KLEBER KLEBER-DYNAXER HP4	205/50//R17 - 93W / 2 mm
	KLEBER KLEBER-DYNAXER HP4	205/50//R17 - 93W / 2 mm

Cosmetic Damage

21 Danni



11 Danni



Component		Damage	Comments
1	Panel Filling / Front Right	Interior / Broken	
2	Center Console	Interior / Worn - out	
3	Roof Upholstery	Interior / Broken	
4	Panel Filling / Front Left	Interior / Broken	
5	Floor Carpet	Interior / Worn - out	
6	Seat / Front Left	Interior / Worn - out	
7	Panel Filling / Back Left	Interior / Broken	
8	Trunk Upholstery / Back	Interior / Scratched	
9	Luggage Space Cover / Back	Interior / Broken	
10	Tailgate Upholstery / Back	Interior / Scratched	
11	Panel Filling / Back Right	Interior / Broken	
12	Rim / Front Right	Out of Bodywork / Scratch	

13	Tire / Front Right	Tire
14	Mirror Repeater / Right	Glass Break
15	Mirror Shell / Front Right	Bodywork / Breakage
16	Rocker Panel / Center Right	Bodywork / Dent
17	Bumper / Front	Bodywork / Dent
18	Hood	Paint / Scratch / Line
19	Windshield / Front	Glass Break / Impact
20	Fender / Front Left	Bodywork / Dent
21	Rim / Front Left	Out of Bodywork / Scratch
22	Barrel / Front Left	Bodywork / Breakage
23	Door / Front Left	Paint / Scratch / Line
24	Door / Back Left	Bodywork / Dent
25	Rocker Panel / Center Left	Bodywork / Dent
26	Rim / Back Left	Out of Bodywork / Scratch
27	Fender / Back Left	Bodywork / Dent
28	Bumper / Back	Bodywork / Dent
29	Pillar / Front Right	Bodywork / Dent / Hail Area
30	Rim / Back Right	Out of Bodywork / Scratch
31	Door / Back Right	Paint / Scratch / Line
32	Fender / Back Right	Paint / Scratch / Line



1. Panel Filling / Front Right
Interior / Broken -



2. Center Console
Interior / Worn - out -



3. Roof Upholstery
Interior / Broken -



4. Panel Filling / Front Left
Interior / Broken -



5. Floor Carpet
Interior / Worn - out -



6. Seat / Front Left
Interior / Worn - out -




7. Panel Filling / Back Left
Interior / Broken -



8. Trunk Upholstery / Back
Interior / Scratched -



9. Luggage Space Cover / Back
Interior / Broken -




10. Tailgate Upholstery / Back
Interior / Scratched -



11. Panel Filling / Back Right
Interior / Broken -



12. Rim / Front Right
Out of Bodywork / Scratch -




13. Tire / Front Right
Tire - Replace



14. Mirror Repeater / Right
Glass Break -



15. Mirror Shell / Front Right
Bodywork / Breakage -




16. Rocker Panel / Center Right
Bodywork / Dent -



17. Bumper / Front
Bodywork / Dent -



18. Hood
Paint / Scratch / Line -



19. Windshield / Front
Glass Break / Impact -



20. Fender / Front Left
Bodywork / Dent -




21. Rim / Front Left
Out of Bodywork / Scratch -




22. Barrel / Front Left
Bodywork / Breakage -



23. Door / Front Left
Paint / Scratch / Line -




24. Door / Back Left
Bodywork / Dent -



25. Rocker Panel / Center Left
Bodywork / Dent -



26. Rim / Back Left
Out of Bodywork / Scratch -



27. Fender / Back Left
Bodywork / Dent -



28. Bumper / Back
Bodywork / Dent -




29. Pillar / Front Right
Bodywork / Dent / Hail Area -



30. Rim / Back Right
Out of Bodywork / Scratch -



31. Door / Back Right
Paint / Scratch / Line -



32. Fender / Back Right
Paint / Scratch / Line -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	!

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	!		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
Gearbox			
Manual Gearbox	✓		

✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage

! Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

☐ Not tested