

Vehicle details

VIN	WF0EXXTTR ELY64866	Brand	FORD	Maintenance date	-
Licence Plate	SKE713	Model	Transit 2.0 Tdci 170le Van Rwd L4h3 3.	Maintenance mileage	-
Registration date	18/11/2020	Year	2020	Exterior Color	White Solid
Odometer	161 313 km	Engine size	1995	interior Color	Grey
Fuel	Diesel	Body Type	Panel van	Next technical inspection	24/10/2026
Seats	3	Transmission	Manual	CO2	-
Doors	4	Gears	6		

Inspection Details

Inspection date	18/02/2025	Inspection loc.	Járműdepó Kft.		
					
					
					
					
					
					
					

Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Anti-fog lights	✓
Front radars	✓
Reversing radars	✓

Removable element

Spare wheel (wheel & tyre)	✓
In-car tools	✓
Jack	✓


Technical Document

Service manual holder	✗
User manual	✗
Key	✓
Remote key	✓

Tyres

Winter kit

Hankook 235/65/16 R Winter 8.9 mm



Hankook 235/65/16 R Winter 8.0 mm



Hankook 235/65/16 R Winter 9.0 mm



Hankook 235/65/16 R Winter 9.0 mm

Exterior

1



Part	Sill
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

6



Part	3rd brake light
Position	-
Damages	Broken
Severity	-
Repair mode	Replace

9



Part	Wheelcap 16"
Position	Back right
Damages	Missing
Severity	-
Repair mode	Replace

10



Part	Wheelcap 16"
Position	Back left
Damages	Missing
Severity	-
Repair mode	Replace

12



Part	Roof
Position	Front
Damages	Scratched
Severity	-
Repair mode	For info

13



Part	Roof post A/B/C
Position	Front right
Damages	Stone impact
Severity	-
Repair mode	For info

14



Part	Wing
Position	Front right
Damages	Stone impact
Severity	-
Repair mode	For info

15



Part	Wing moulding
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Replace

16



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Replace

17



Part	Turning signal side
Position	Left
Damages	Stained/dirty
Severity	-
Repair mode	For info

18



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

19



Part	Side panel
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

20



Part	Rear light (wing)
Position	Back left
Damages	Stained/dirty
Severity	-
Repair mode	For info

●

●

●

21



Part	C-pillar
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

●

●

22



Part	Side panel
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

●

●

●

●

23



Part	Wing moulding
Position	Side right
Damages	Scratched
Severity	-
Repair mode	Replace

●

●

●

24



Part	Door
Position	Side right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

●

●

●

●

●

●

●

25



Part	Door moulding
Position	Side right
Damages	Scratched
Severity	-
Repair mode	For info

●

●

26



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

●

●

27



Part	Door
Position	Front right
Damages	Dented
Severity	-
Repair mode	For info

●

●

30



Part	Sticker removal
Position	-
Damages	Not carried out
Severity	-
Repair mode	To be carried out

●

●

●

Interior damage

2



Part

Interior cleaning

Position

-

Damages

Not carried out

Severity

-

Repair mode

To be carried out

3



Part

Steering wheel

Position

-

Damages

Scratched

Severity

-

Repair mode

For info

5



Part

Load cover

Position

-

Damages

Misaligned

Severity

-

Repair mode

Adjust

7



Part	Glove compartment door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

8



Part	Ceiling Shelf
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info

28



Part	Service manual holder
Position	-
Damages	Missing
Severity	-
Repair mode	For info

29



Part	User manual
Position	-
Damages	Missing
Severity	-
Repair mode	For info

Others

4



Part	Other technic
Position	-
Damages	Misaligned
Severity	-
Repair mode	Adjust
Szervókormány	

11



Part	Other accessory
Position	-
Damages	Not conform
Severity	-
Repair mode	For info
Reg. matrica	

31



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

Comments

Akku gyenge. Csak külső áramforrással indítható.
Kormány szervó nem megy.