

Vehicle details

VIN	WF0EXXTTR EMR79815	Brand	FORD	Maintenance date	-
Licence Plate	SVP187	Model	Transit 2.0 Tdci 170le Van Rwd L4h3 3.	Maintenance mileage	-
Registration date	06/08/2021	Year	2021	Exterior Color	White Solid
Odometer	118 662 km	Engine size	1995	interior Color	Grey
Fuel	Diesel	Body Type	Panel van	Next technical inspection	06/08/2025
Seats	3	Transmission	Manual	CO2	-
Doors	4	Gears	6		

Inspection Details

Inspection date	11/02/2025	Inspection loc.	Járműdepó Kft.		
					
					
					
					
					
					
					

Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Anti-fog lights	✓
Front radars	✓
Reversing radars	✓

Removable element

Spare wheel (wheel & tyre)	✓
Toolkit	✓
Jack	✓


Technical Document

Service manual holder	✗
User manual	✗
Key	✓
Remote key	✓

Tyres

Winter kit

Semperit 235/65/16 Winter 6.1 mm



Semperit 235/65/16 Winter 5.6 mm



Kumho 235/65/16 Winter 5.4 mm



Kumho 235/65/16 Winter 4.4 mm

Exterior

1



Part	Sill
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

2



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

3



Part	Wheelcap 16"
Position	Front right
Damages	Missing
Severity	-
Repair mode	Replace

4



Part	Roof post A/B/C
Position	Front right
Damages	Stone impact
Severity	-
Repair mode	For info

5



Part	Wing
Position	Front right
Damages	Stone impact
Severity	-
Repair mode	For info

6



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Replace

7



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	For info

8



Part	Wing
Position	Front left
Damages	Stone impact
Severity	-
Repair mode	For info

9



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

10



Part	Side panel
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

11



Part	Door moulding
Position	Side right
Damages	Scratched
Severity	-
Repair mode	For info

12



Part	Door
Position	Side right
Damages	Scratched
Severity	-
Repair mode	For info

13



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

14



Part	Door moulding
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

15



Part	Sticker removal
Position	-
Damages	Not carried out
Severity	-
Repair mode	To be carried out

16



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

Interior damage

17		<table> <tr><td>Part</td><td>Service manual holder</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Service manual holder	Position	-	Damages	Missing	Severity	-	Repair mode	For info	18		<table> <tr><td>Part</td><td>User manual</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	User manual	Position	-	Damages	Missing	Severity	-	Repair mode	For info
Part	Service manual holder																								
Position	-																								
Damages	Missing																								
Severity	-																								
Repair mode	For info																								
Part	User manual																								
Position	-																								
Damages	Missing																								
Severity	-																								
Repair mode	For info																								
19		<table> <tr><td>Part</td><td>Glove compartment cover</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Glove compartment cover	Position	-	Damages	Scratched	Severity	-	Repair mode	For info													
Part	Glove compartment cover																								
Position	-																								
Damages	Scratched																								
Severity	-																								
Repair mode	For info																								