



# FORD Kuga

## Kuga 2.5 Duratec PHEV

VIN NO WF0FXXWPMHLE30518  
Registration Number PMHLE30518



|              |                      |                         |                          |
|--------------|----------------------|-------------------------|--------------------------|
| MOT Date     | Number of Owners     | Number of Keys          | Odometer Reading         |
| 2026-06-01   | 1                    | 2                       | 75886 km                 |
| Last Service | Last Service Mileage | First Registration Date | Country First Registered |
| 2024-07-18   | 60437                | 2021-05-12              | Germany                  |

### Inspection Report Summary

|                         |                                       |                |                 |
|-------------------------|---------------------------------------|----------------|-----------------|
| Customer                | BCA Online                            | Report Number  | P20250926120413 |
| Inspection Date / Place | 2025-09-26 / ARS Altmann AG Riedstadt | Cosmetic Grade | 3               |

### Vehicle Summary

|                    |                                          |                    |                   |
|--------------------|------------------------------------------|--------------------|-------------------|
| Vehicle Condition  | Runner                                   | VAT Type           | Margin            |
| Fuel Type          | Plug - in Hybrid Electric Vehicle Petrol | Road Worthy        | Yes               |
| Colour             | Grey                                     | Engine Size (cc)   | 2488              |
| Engine Size        | 2.5                                      | No of Doors        | 5                 |
| Body Type          | SUV                                      | Drive Train        | Front             |
| Seat Colour        |                                          | No of Seats        | 5                 |
| Seat Covering Name |                                          | Seat Covering      | Synthetic Leather |
| Charging Cables    | OUC + Type 2                             | WLTP CO2 Emissions |                   |
| Gearbox Type       | Automatic                                |                    |                   |

### Vehicle History & Documents


|                        |                              |                      |    |
|------------------------|------------------------------|----------------------|----|
| Service Book Available | Computer Print Out Available | Next Service Mileage | km |
| Previous Usage         |                              | Imported             | No |
| Manufacturer Warrenty  |                              |                      |    |











Equipment

|                                   |                        |                        |                               |
|-----------------------------------|------------------------|------------------------|-------------------------------|
| Tinted Glass                      | USB Socket             | Alloys wheels          | Bluetooth telephone interface |
| Digitaldashboard                  | Head up Display        | Remote central locking | Satellite navigation          |
| Electrically folding wing mirrors | Leather steering wheel | Radio                  | Trip Computer                 |
| Airbag Status                     | Anti-lock braking      | Cruise control         | Front parking sensors         |
| Remote adjusting wing mirrors     | Reversing Camera       | Stability control      | Electrictailgate              |
| LED Headlamps                     | Rear parking sensors   |                        |                               |

Equipment Details


|                        |                           |                  |       |
|------------------------|---------------------------|------------------|-------|
| Air Conditioning       | Dual Zone Climate Control | Alloy Wheel Size | 18    |
| Extra Wheel / Tyre Set | Winter Tyres - Alloy      | Seat Heating     | Front |

Wheels & Tyres


|                            |   |                            |   |
|----------------------------|---|----------------------------|---|
| Extra Wheel - 1 Tyre Depth | 5 | Extra Wheel - 2 Tyre Depth | 5 |
| Extra Wheel - 3 Tyre Depth | 5 | Extra Wheel - 4 Tyre Depth | 5 |
| Right Front Tyre Depth     | 4 | Left Front Tyre Depth      | 4 |
| Right Rear Tyre Depth      | 4 | Left Rear Tyre Depth       | 4 |

Cosmetic Damage

7 Schäden




0 Schäden



| Component             | Damage                          | Comments |
|-----------------------|---------------------------------|----------|
| 1 Hood                | Paint / Stone Chip              |          |
| 2 Bumper / Front      | Paint / Scratch / Scuff         |          |
| 3 Bumper / Front      | Paint / Scratch / Scuff         |          |
| 4 Bumper / Back       | Paint / Scratch / Scuff         |          |
| 5 Rear Window / Back  | Glass Break / Scratch / Scratch |          |
| 6 Fender / Back Right | Bodywork / Dent / Dent          |          |
| 7 Fender / Back Right | Bodywork / Dent / Dent          |          |





1. Hood  
Paint / Stone Chip -




2. Bumper / Front  
Paint / Scratch / Scuff -




3. Bumper / Front  
Paint / Scratch / Scuff -




4. Bumper / Back  
Paint / Scratch / Scuff -



5. Rear Window / Back  
Glass Break / Scratch / Scratch -



6. Fender / Back Right  
Bodywork / Dent / Dent -



7. Fender / Back Right  
Bodywork / Dent / Dent -



## Mechanical Condition

### Engine

|                     |   |                     |   |
|---------------------|---|---------------------|---|
| Engine Starts       | ✓ | Engine Status / EML | ✓ |
| Engine Leak Visible | ✓ |                     |   |

### Control Lights

|                                 |   |                                              |   |
|---------------------------------|---|----------------------------------------------|---|
| ABS Warning Light               | ✓ | ESP Fault/Traction Control Malfunction Light | ✓ |
| Airbag Warning Light            | ✓ | Oil Pressure Warning Light                   | ✓ |
| Brake Warning Light             | ✓ | Power Steering Warning Light                 | ✓ |
| Alternator / Battery            | ✓ | No Dashboard Lights                          | ✓ |
| Display Defect                  | ✓ | Service Light                                | ✓ |
| Tire Pressure Monitoring System | ✓ |                                              |   |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Hybrid/EV

|                     |   |
|---------------------|---|
| Hybrid System Fault | ✓ |
|---------------------|---|

### Equipments Test

|                                       |   |                     |   |
|---------------------------------------|---|---------------------|---|
| Other Equipments                      | ✓ | Central Locking     | ✓ |
| Main & Spare Keys Functioning         | ✓ | Electric Windows    | ✓ |
| Navigation System                     | ✓ | Audio Equipment     | ✓ |
| Parking Sensors / Cameras Functioning | ✓ | AC / Heating System | ✓ |

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

## Test Drive Inspection

| Engine                                                                                               |   |                                               |   |
|------------------------------------------------------------------------------------------------------|---|-----------------------------------------------|---|
| Engine Noise                                                                                         | ✓ | Fume Quantity                                 | ✓ |
| Power Loss                                                                                           | ✓ | The Gears Scratch / Skip / Abnormal Operation | ✓ |
| Brake                                                                                                |   |                                               |   |
| Brake System Anomaly                                                                                 | ✓ |                                               |   |
| Steering Wheel                                                                                       |   |                                               |   |
| Steering   Noise / Anomaly                                                                           | ✓ |                                               |   |
| General                                                                                              |   |                                               |   |
| Test Driven Status                                                                                   | ✓ |                                               |   |
| ✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i> |   |                                               |   |
| ! <i>Damages or malfunction detected that requires repairs by the buyer</i>                          |   |                                               |   |
| NA <i>Not applicable</i>                                                                             |   |                                               |   |
| ☐ <i>Not tested</i>                                                                                  |   |                                               |   |

## Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)