


Vehicle details

VIN	WF0JXXGAH JJM42316	Brand	FORD	Maintenance date	-
Licence Plate	TJ-27-2B	Model	FIESTA 1.0 EcoBoost 74kW ActieAuto 5d ST-line + Na	Maintenance mileage	-
Registration date	05/09/2018	Year	2018	Exterior Color	White Solid
Odometer	69 434 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	02/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Vredestein 215/40/17 Winter 7.0 mm



Vredestein 215/40/17 Winter 7.0 mm



Vredestein 215/40/17 Winter 7.5 mm

Vredestein 215/40/17 Winter 7.5 mm

Exterior

1



Part

Alloy wheel 17"

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

2



Part

Door

Position

Back left

Damages

Dented

Severity

Number > 2

Repair mode

Smart Repair

4



Part

Bumper

Position

Back

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

5



Part

Alloy wheel 17"

Position

Back right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

6



Part

Step plate

Position

Back right

Damages

Scratched

Severity

-

Repair mode

For info

7



Part

Exterior door mirror shell

Position

Front right

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

8



Part

Alloy wheel 17"

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

9



Part

Bumper

Position

Front

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

10



Part

Alloy wheel 17"

Position

Back left

Damages

Scratched

Severity


-

Repair mode

Lumpsum repair

Interior damage

2



Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning