


Vehicle details

VIN	WF0JXXGAH JJM47775	Brand	FORD	Maintenance date	-
Licence Plate	TJ-09-2K	Model	FIESTA 1.0 EcoBoost 74kW ActieAuto 5d ST-line + Na	Maintenance mileage	-
Registration date	24/08/2018	Year	2018	Exterior Color	Grey Metallic
Odometer	127 616 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	26/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 205/45/17 Summer 7.0 mm		Michelin 205/45/17 Summer 7.0 mm	
Hankook 205/45/17 Summer 6.0 mm		Hankook 205/45/17 Summer 6.5 mm	

Exterior

1



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

● ● ● ●

2



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

● ●

3



Part	Wing
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

● ●

4



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

● ●

5



Part	Alloy wheel 17"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

● ●

6



Part	Alloy wheel 17"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

● ●

7



Part	Wing
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

● ● ● ● ●

8



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

● ● ● ● ● ● ●